

# Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875  
Tel: 93290237 Email: claims\_rar@bifrotauto.com

SJE : \_\_\_\_\_  
Date of Survey : \_\_\_\_\_  
Date of ReSurvey: \_\_\_\_\_  
Contacts : \_\_\_\_\_

Vehicle Nos : **SMU 5708U**  
Made : Honda  
Model : HRV 1.5 LX CVT  
Chassis No : \_\_\_\_\_

## \* AGREED Cost Of Repair and Repair Day/s with SJE \*

Amount: \_\_\_\_\_

Working Day: \_\_\_\_\_

| Nos. | PARTS                                                | Qty | Unit S\$    | TOTAL S\$   |
|------|------------------------------------------------------|-----|-------------|-------------|
| 1    | Front Bumper <del>CRA</del> / BR                     | 1   | \$ 975.50   | \$ 975.50   |
| 2    | Front Bumper Side Retainer RH <del>CRA</del> /       | 1   | \$ 30.20    | \$ 30.20    |
| 3    | Front Bumper Side Retainer LH X nn                   | 1   | \$ 30.20    | \$ 30.20    |
| 4    | Front Bumper Bracket RH X nn                         | 1   | \$ 32.50    | \$ 32.50    |
| 5    | Front Bumper Bracket LH X nn                         | 1   | \$ 32.50    | \$ 32.50    |
| 6    | Front Bumper Fog Lamp RH X nn                        | 1   | \$ 392.70   | \$ 392.70   |
| 7    | Front Bumper Fog Lamp Garnish RH X nn                | 1   | \$ 50.00    | \$ 50.00    |
| 8    | Front Bumper Tow Cover X nn                          | 1   | \$ 29.80    | \$ 29.80    |
| 9    | Front Bumper Reinforcement X nn                      | 1   | \$ 386.00   | \$ 386.00   |
| 10   | Front Bumper Lower Grille X nn                       | 1   | \$ 108.30   | \$ 108.30   |
| 11   | Front Bumper Lower Spoiler <del>CRA</del> -          | 1   | \$ 419.10   | \$ 419.10   |
| 12   | Front Bumper Lower Rubber X nn                       | 1   | \$ 115.40   | \$ 115.40   |
| 13   | Front Grille Base X nn                               | 1   | \$ 418.00   | \$ 418.00   |
| 14   | Front Grille Outer Chrome X nn                       | 1   | \$ 260.70   | \$ 260.70   |
| 15   | Front Grille Emblem X nn                             | 1   | \$ 36.70    | \$ 36.70    |
| 16   | Front Grille Upper Centre Bracket X nn               | 1   | \$ 50.10    | \$ 50.10    |
| 17   | Front Headlamp Assembly RH <del>CRA</del> -          | 1   | \$ 1,980.00 | \$ 1,980.00 |
| 18   | Front Headlamp Assembly LH X nn                      | 1   | \$ 1,980.00 | \$ 1,980.00 |
| 19   | Front Headlamp Lower Bracket RH X <del>nn</del> / BR | 1   | \$ 41.80    | \$ 41.80    |
| 20   | Front Headlamp Lower Bracket LH X nn                 | 1   | \$ 41.80    | \$ 41.80    |
| 21   | Front Bonnet X nn                                    | 1   | \$ 981.50   | \$ 981.50   |
| 22   | Front Bonnet Lock X nn                               | 1   | \$ 119.30   | \$ 119.30   |
| 23   | Front Bonnet Insulator X nn                          | 1   | \$ 167.50   | \$ 167.50   |
| 24   | Front Bonnet Hinge RH X nn                           | 1   | \$ 53.40    | \$ 53.40    |
| 25   | Front Bonnet Hinge LH X nn                           | 1   | \$ 53.40    | \$ 53.40    |
| 26   | Front Support Panel X nn                             | 1   | \$ 649.20   | \$ 649.20   |
| 27   | Aircon Condenser X nn                                | 1   | \$ 657.90   | \$ 657.90   |
| 28   | Radiator X nn                                        | 1   | \$ 1,623.60 | \$ 1,623.60 |
| 29   | Front Fender RH <del>Ren</del> + R X                 | 1   | \$ 471.60   | \$ 471.60   |
| 30   | Front Fender Inner Cowling RH <del>Ren</del> X nn    | 1   | \$ 170.50   | \$ 170.50   |
| 31   | Front Fender Wheel Arch Garnish RH <del>CRA</del> /  | 1   | \$ 206.30   | \$ 206.30   |
| 32   | Front Wheel Rim RH CUT /                             | 1   | \$ 836.20   | \$ 836.20   |

524 ✓

✓

387 ✓

1859 ✓

✓

✓

500 ✓

|    |                                          |      |   |    |        |    |        |
|----|------------------------------------------|------|---|----|--------|----|--------|
| 33 | Front Wheel Hub RH                       | X nn | 1 | \$ | 211.30 | \$ | 211.30 |
| 34 | Front Wheel Hub Bearing RH               | X nn | 1 | \$ | 155.90 | \$ | 155.90 |
| 35 | Front Shock Absorber RH                  | X nn | 1 | \$ | 387.60 | \$ | 387.60 |
| 36 | Front Lower Arm RH                       | X nn | 1 | \$ | 444.80 | \$ | 444.80 |
| 37 | Front Stabilizer Link                    | X nn | 1 | \$ | 53.40  | \$ | 53.40  |
| 38 | Front Knuckle Arm RH                     | X nn | 1 | \$ | 280.70 | \$ | 280.70 |
| 39 | Tie Rod End RH                           | X nn | 1 | \$ | 82.70  | \$ | 82.70  |
| 40 | Front Door Side Mirror Assembly RH       | X nn | 1 | \$ | 667.20 | \$ | 667.20 |
| 41 | Front Door Side Mirror Cover RH          | X nn | 1 | \$ | 71.20  | \$ | 71.20  |
| 42 | Front Door RH                            | X nn | 1 | \$ | 903.20 | \$ | 903.20 |
| 43 | Front Door Upper Hinge RH                | X nn | 1 | \$ | 38.50  | \$ | 38.50  |
| 44 | Front Door Lower Hinge RH                | X nn | 1 | \$ | 40.90  | \$ | 40.90  |
| 45 | Front Door Outer Glass Moulding RH       | X nn | 1 | \$ | 55.60  | \$ | 55.60  |
| 46 | Front Door Lock RH                       | X nn | 1 | \$ | 225.00 | \$ | 225.00 |
| 47 | Front Door Weatherstrip RH ( Top )       | X nn | 1 | \$ | 85.00  | \$ | 85.00  |
| 48 | Front Door Weatherstrip RH ( Lower )     | X nn | 1 | \$ | 25.00  | \$ | 25.00  |
| 49 | Front Door Glass Channel RH              | X nn | 1 | \$ | 88.00  | \$ | 88.00  |
| 50 | Front Door Glass Regulator with Motor RH | X nn | 1 | \$ | 382.00 | \$ | 382.00 |
| 51 | Front Door Inner Trim Board RH           | X nn | 1 | \$ | 650.00 | \$ | 650.00 |
| 52 | Rocker Panel Garnish RH                  | X nn | 1 | \$ | 415.30 | \$ | 415.30 |

3548.30  
-20%  
2838.64

20%

|                      |           |                  |
|----------------------|-----------|------------------|
| Parts Sub Total :    | \$        | 18,665.00        |
| Discount             | \$        | 3,733.00         |
| <b>PARTS TOTAL :</b> | <b>\$</b> | <b>14,932.00</b> |

| Nos.                        | SPECIAL NETT                                 | Qty  | Unit S\$ | TOTAL S\$          |
|-----------------------------|----------------------------------------------|------|----------|--------------------|
| 1                           | Front Number Plate                           | X nn | 1        | \$ 50.00           |
| 2                           | Front Bumper Clips - Set                     | ml ✓ | 1        | \$ 50.00           |
| 3                           | Front Bumper Grille Clips - Set              | X nn | 1        | \$ 30.00           |
| 4                           | Front Bumper Fog Lamp Garnish RH Clips - Set | X nn | 1        | \$ 30.00           |
| 5                           | Front Grille Base Clips - Set                | X nn | 1        | \$ 50.00           |
| 6                           | Front Bonnet Insulator Clips - Set           | X nn | 1        | \$ 50.00           |
| 7                           | Front Fender Inner Cowling RH Clips - Set    | X nn | 1        | \$ 40.00           |
| 8                           | Front Door Inner Trim Board RH Clips - Set   | X nn | 1        | \$ 50.00           |
| 9                           | Rocker Panel Garnish RH Clips - Set          | X nn | 1        | \$ 50.00           |
| 10                          | Front Bonnet Sealant                         | X nn | 1        | \$ 150.00          |
| 11                          | Front Fender RH Sealant                      | X nn | 1        | \$ 150.00          |
| 12                          | Front Door RH Sealant                        | X nn | 1        | \$ 150.00          |
| 13                          | Radiator Coolant                             | X nn | 1        | \$ 60.00           |
| 16                          | Front Tyre RH                                | X nn | 1        | \$ 350.00          |
| <b>SPECIAL NETT TOTAL :</b> |                                              |      |          | <b>\$ 1,260.00</b> |

30

| Nos. | LABOUR                              | TOTAL S\$   |
|------|-------------------------------------|-------------|
| 1    | To Panel Beat, Remove & Refix Parts | \$ 1,600.00 |
| 2    | To Spray Paint Affected Areas       | \$ 1,600.00 |

30

400

400

400

|    |                                                                          |                       |                    |    |
|----|--------------------------------------------------------------------------|-----------------------|--------------------|----|
| 3  | Wiring & Bulb Check                                                      | \$                    | 100.00             | 30 |
| 4  | To Transfer Front Door RH Mechanism                                      | \$                    | 150.00             | X  |
| 5  | To Remove & Refix Aircon Condenser and Top Up Gas                        | \$                    | 150.00             | X  |
| 6  | To Remove & Refix Radiator and Pressure Test                             | \$                    | 150.00             | X  |
| 7  | To apply anti rust on affected parts                                     | \$                    | 120.00             | 30 |
| 8  | To Conduct Four Wheel Alignment                                          | \$                    | 150.00             | X  |
| 9  | To Remove & Refix Front Undercarriage                                    | \$                    | 350.00             | X  |
| 10 | To Remove & Refix Front Tyre and Conduct Wheel Balancing                 | \$                    | 150.00             | X  |
| 11 | To Conduct Water Leak Test                                               | \$                    | 100.00             | X  |
| 12 | To Send for Diagnostic and Reset Control Unit. Programming & Calibration | \$                    | 480.00             | X  |
|    |                                                                          | <b>LABOUR TOTAL :</b> | <b>\$ 5,100.00</b> |    |

860

4 days

L/S 23/2/23

1 hr  
440 pm

PARTS TOTAL : \$ 14,932.00

SPECIAL NETT TOTAL : \$ 1,260.00

LABOUR TOTAL : \$ 5,100.00

**GRAND TOTAL : \$ 21,292.00**

3728.64

L/S - 2982.91  
= 3000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: