



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22005473/Rvy3e2-1	Date: 27/03/2023
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 8413U		Veh. Inspected	SMM 4558J
Policy No.			Coverage (\$)	0.00
Claim No.	21/22/22/VC00/025905		Excess (\$)	0.00
Assign From	GERALD POH		Assign Date	22/02/2023
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6 ELE		c.c	1598
Engine No.	HIDDEN		Year of Reg.	2019
Chassis No.	MR053REH604598029		Colour	WHITE
Odometer	256131 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45Z R17	ECO819	6 mm	
L/H Front Tyre	215/45Z R17	ECO819	6 mm	
R/H Rear Tyre	215/45Z R17	ECO819	6 mm	
L/H Rear Tyre	215/45Z R17	ECO819	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/06/2022		Inspection Date	09/06/2022
Survey held at	A T PERFORMANCE 160 SIN MING DRIVE #07-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	