

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 27 Feb 2023

**Preliminary Advice**

Vehicle No	: SMK8251C	Accident Date	: 18/02/2023
Make	: AUDI A6	Policy No.	: DMPCSNA00155932202
Assignment Date	: 22/02/2023	Excess	: S\$0.00
Date of Inspection	: 24/02/2023	Est. Duration of Repair	: 7
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,343.69
Revised Amount	:S\$	22,886.69
Check Items (Estimated)	:S\$	6,190.00
Total	:S\$	29,076.69
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	31,540.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,460.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Repairer able to repair the vehicle at repair cost not more than \$13,000.00 on lump sum basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.