

ASS. REC. BY:

REF:

C72/23002052/kw

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.6.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

09/24

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKS 40338

Yr Regn:

09, 09

Type: M.Caf / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1595

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

402149

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH M150 46208S 200928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

one Service

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel : 9695 5547 e-mail : ngs motorsportpteltd@gmail.com

Reg No: 201812604N

09/01/2023

*Not Authorized
Repair After Painting
2 days*

China TaiPing Insurance (S) Pte Ltd
Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 19/12/2022
VEH NO.: SKS4033Z & SNH2928C
CLAIMS AGAINST SNH2928C
VEH NO.: SKS4033Z (IN WORKSHOP)

We submit herewith our direct third party claim estimate quotation as follow:-
Replacement parts: HD CV

- 1 Frt Door Assy RH - Repair
- 1 Rr Door Assy RH - Repair
- 1 Side Mirror RH

\$	688.00	X
\$	688.00	
Less 20%	\$	(137.60)

To remove all damaged part with all necessary components/attachments.
Straighten chassis member, repair/reshape dented body panel in accordance
with factory specifications. Replace/reposition damaged parts, refit align into
position. Refix all necessary components/attachments.

\$ 700.00 x 50%

Spray paint on replace/repair body parts.

\$ 800.00 600

To remove/refit wire harness, all related connector, check proper function.

\$	50.00	X
\$	2,100.40	

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD
EVELYN NG

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: