

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming Auto Centre

Tel: 6452 7019

Not Attached
Penny Bepina
3-4 days

Vehicle Insured : SDV 1095 G
Accident Date : 04-Dec-2022

No. : 32685

Date : 14-Dec-2022

Our Ref : 022457 (ALLIANZ) / QUEK

PAGE : 1

CHUA WEE SIANG (MR)
Singapore

ESTIMATED COST OF REPAIR FOR HONDA FREED (1496CC) (2021) SNC7016C

1 pc rear bumper	819.40 X
1 pc tailgate	1,032.30 ✓
1 pc tailgate 'H' logo	32.30 ✓
1 pc tailgate 'Freed' emblem	52.60 ✓
1 pc tailgate glass moulding	95.60 ✓
2 pcs reverse sensor assy (original) @ S\$310.00	620.00 X
2 pcs reverse sensor outer @ S\$ 90.00	180.00 X

2,832.20

Less 20% : -566.44

2,265.76

1 pc tailgate glass sealant
1 pc tailgate glass damping seal

40.00 sn ✓
20.00 sn ✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

3201
380.00

To putty and respray on affected
portions.

4001
480.00

To apply undersealing

80.00 301

To remove and refit reverse sensor
assy.

60.00 501

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

Total : S\$ 3,445.76

Singapore Dollars Three Thousand Four Hundred and Forty Five and Cents Seventy Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Driver
NRIC No
Of Birth

14/11/1900
Indoor