



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303899

INV Date 19/06/2023

Reference CC4/LPC23002057/Uya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJE 298M
Insured Veh. GBD 3417S
Claim No. 22/23/23/VC05/027017
Policy No. Z22VC05013229
Accident Date 21/02/2023
Inspection Date 23/02/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC23002057/Uya3q2 Date: 19/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 3417S	Veh. Inspected	SJE 298M
	Policy No.	Z22VC05013229	Coverage (\$)	0.00
	Claim No.	22/23/23/VC05/027017	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	23/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W. X3 (A)	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WBATR12090LS31271	Colour	GREY
	Odometer	67410 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/50 R19	PIRELLI	7 mm
	L/H Front Tyre	245/50 R19	PIRELLI	7 mm
	R/H Rear Tyre	245/50 R19	PIRELLI	7 mm
	L/H Rear Tyre	245/50 R19	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & REAR WINDSCREEN. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/02/2023	Inspection Date	23/02/2023
	Survey held at	JUZZ PERFORMANCE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-51/52 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 298M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BMW TRUNK LID	BADLY DENTED	3,075.00	2,112.45
1	BMW REAR BUMPER	DISTORTED	2,250.00	1,536.45
1	BMW REAR BUMPER TRIM PANEL BOTTOM	DISTORTED	760.00	365.85
1	BMW COVER ,TOW FITTING REAR	TORN	154.00	60.00
1	BMW KIT,MOUNT FOR PDC/PMA SENSOR REAR	SHORTED	260.00	260.00
1	BMW GUIDE FOR BUMPER SIDE LH	NOT NECESSARY	280.00	-
1	BMW GUIDE FOR BUMPER SIDE CENTRE	CRACKED	280.00	280.00
1	BMW GUIDE BUMPER ,RIGHT	CRACKED	240.00	182.00
1	BMW REAR BUMPER CARRIER	BENT	1,540.00	800.70
1	BMW LOWER TAIL LID TRIM PANEL	NOT NECESSARY	300.00	-
1	BMW UPPER TRUNK LID TRIM PANEL	CRACKED	300.00	300.00
1	BMW INNER LEFT ,TRIM PANEL FOR TRUNK	NOT NECESSARY	190.00	-
1	BMW INNER RIGHT ,TRIM PANEL FOR TRUNK	CUT	190.00	162.00
1	BMW LEFT TRIM DRIP RAIL	NOT NECESSARY	100.00	-
1	BMW RIGHT TRIM DRIP RAIL	NOT NECESSARY	100.00	-
1	BMW TAIL LAMP RH OUT (LED)	CRACKED	840.00	612.05
1	BMW TAIL LAMP RH IN (LED)	BROKEN	560.00	428.45
1	BMW REAR LH REFLECTOR	NOT NECESSARY	60.00	-
1	BMW REAR RH REFLECTOR	SCRATCHED	60.00	60.00
1	BMW STORAGE TROUG LUGGAGE TRUNK FLOOR	NOT NECESSARY	660.00	-
1	BMW SUPPORT LUGGAGE COMPARTMENT FLOOR PANEL	NOT NECESSARY	180.00	-
1	BMW LOADING EDGE TRIM	NOT NECESSARY	460.00	-
1	BMW REAR MUFFLER	BENT / TWISTED	2,100.00	1,645.00
1	BMW REAR MUFFLER	BENT	260.00	260.00
1	BMW REAR WINDSCREEN	SHATTERED	2,200.00	1,107.25
1	BMW REAR WINDOW WIPER MOTOR	JAMMED	1,000.00	680.00
1	BMW REAR WINDOW WIPER ARM	CUT	190.00	190.00
1	BMW REAR WIPER BLADE	NOT NECESSARY	96.00	-
10	BMW CLIPS NATUR @\$2.00	NOT NECESSARY	20.00	-
10	BMW CLIPS @\$12.00	NOT NECESSARY	120.00	-

Report Ref No. CC4/LPC23002057/Uya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	REAR BUMPER CLIPS @\$4.00	NECESSARY	32.00	32.00
1	TRUNK LID SEALANT	NECESSARY	75.00	50.00
1	REAR NUMBER PLATE	NOT NECESSARY	40.00	-
1	REAR NUMBER PLATE CASING	NOT NECESSARY	35.00	-
	LESS 10% DISCOUNT		-	-1,112.42
			19,007.00	10,011.78
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDOW FILM (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & INSTALL ABOVE PARTS AND PANEL BEATING.		850.00	600.00
	LABOUR TO SPRAY PAINT TRUNK LID ,REAR BUMPER & AFFECTED AREAS .		1,400.00	1,000.00
	TUFF COAT.		100.00	30.00
	WIRING & BULB CHECK .		60.00	20.00
	LABOUR TO REMOVE & REFIX CUSHION SEATS /UPHOLSTERY TO FACILITATE REPAIRS .		120.00	80.00
	LABOUR TO REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING.		150.00	50.00
	LABOUR TO PERFORM DIAGNOSTIC CHECKS.	NOT NECESSARY	90.00	-
			2,770.00	1,780.00
GRAND TOTAL			21,877.00	11,891.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,500.00

Report Ref No. CC4/LPC23002057/Uya3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJE 298M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJE 298M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJE 298M

RE-INSPECTION

