

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHA1718G

Make : HYUNDAI

Model : I-40

Date: 02/13/23

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR FENDER RH <i>scr R</i>			\$ 2,171.40 <i>R</i>
1	ROCKER COVER GARNISH RH <i>scr</i>			\$ 732.80
1	REAR DOOR RH <i>BVC</i>			\$ 2,418.80
1	REAR DOOR REGULATOR RH <i>? X</i>			\$ 660.90 <i>X</i>
1	REAR DOOR POWER MOTOR RH <i>? X</i>			\$ 158.60 <i>X</i>
1	FRT DOOR RH <i>scr R</i>			\$ 2,707.70 <i>R</i>
	SUB TOTAL			\$ 8,848.20 <i>3149.60</i>
	LESS 20%			\$ 1,769.64 <i>629.92</i>
	DISCOUNTED TOTAL			\$ 7,078.56 <i>2519.68</i>
	FRT DOOR COMFORT LOGO STICKER RH <i>NEC</i>			\$ 75.00
	REAR DOOR COMFORTDELGRO & APPS STICKER RH <i>NEC</i>			\$ 80.00
				\$ 155.00 <i>Nett</i>
	Labour Charge			
	PANEL BEATING			\$ 900.00 <i>840</i>
	SPRAY PAINTING CHARGE			\$ 1,100.00 <i>750</i>
	TRANSFER OF DOOR			\$ 240.00 <i>80</i>
	TUFF KOTE			\$ 60.00 <i>20</i>
	TOTAL LABOUR			\$ 2,300.00
	ESTIMATE TOTAL			\$ 9,533.56 <i>4364.68</i>
				<i>Wk: 872.93</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

I= 3491.74

4 days ~3500x

L/S

13/2/23

1 r fan

5 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: