



Final Report

Estimate No. : **b1 65120**
Date Estimated : **23/02/2023**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

- **ESTIMATE REPAIR FOR** -
Santosh Narayanlal Radhalal Patel
8 Tampines Street 73
#05-03

- **ACCOUNT** - **224093**
Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Singapore 528826

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMQ6407C	WBA2X920X07E56911	27/11/2019	216i Active Tourer	30795

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear LH door include making good the front LH door, rear LH fender and carrying out necessary repairs caused by the accident	2,550.00		2,550.00
To spray paint both LH doors and rear LH fender	2,958.00		2,958.00
To check electrical wiring system and lightings at the LH section for proper function	168.00		168.00
To transfer lock mechanism from old to new door including conduct check on new door power window system for proper function (x1)	504.00		504.00
To carry out body cavity preservation (x1) (Per panel)	112.00		112.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR LH DOOR	1,285.35	1.00	0.00	1,285.35

SUPPLEMENTARY ITEMS

Total Labour :	6,372.00
Total Parts :	1,285.35
Total Labour & Parts (before GST) :	7,657.35
Deduction for Excess :	600.00
Total Repair Costs less Excess:	7,057.35
GST @8%:	564.59
Grand Total :	7,621.94

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

