

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 14 Mar 2023

Preliminary Advice

Vehicle No	: SMQ6407C	Accident Date	: 14/02/2023
Make	: BMW 216I	Policy No.	: SP2003008571
Assignment Date	: 23/02/2023	Excess	: S\$600.00
Date of Inspection	: 13/03/2023	Est. Duration of Repair	: 6
Inspection At	: PERFORMANCE MOTORS LINTIED (HQ) 303 ALEXANDRA ROAD, SINGAPORE SINGAPORE 159941		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,649.70
Revised Amount	:S\$	7,745.35
Check Items (Estimated)	:S\$	259.95
Total	:S\$	8,005.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	46,986.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,014.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.