



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23002061/Kwy3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROADSINGAPORE 438675		Date:	30/05/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 5830Z	Veh. Inspected	SMC 644Y
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/120	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	24/02/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MR053REH604583449	Colour	METALLIC PEARL WHITE
Odometer	104428 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/45 R17	FALKEN	8 mm
L/H Front Tyre	215/45 R17	FALKEN	8 mm
R/H Rear Tyre	215/45 R17	FALKEN	8 mm
L/H Rear Tyre	215/45 R17	FALKEN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/12/2022	Inspection Date	24/02/2023
Survey held at	160 Sin Ming Drive #02-04 AutoCity		
Repairer	CAR TIMES AUTOLUTION PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	