

ASS. REC. BY:

REF:

SPF / 23002061/kw

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/5

21 Rpm @ 1500. Colours @ 2 days (Red \$2,975.50 / 66%)

Repair Range: \$1,500 - \$1,800 ; 1 weekend

Veh No: _____

SMC 644Y

Yr Regn: _____

06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy A/T/S

c.c

1598

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

104428

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

NR053REH 604583449

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal. _____

P

mm

Rear

R/Bal. _____

P

mm

L/Bal. _____

P

mm

L/Bal. _____

P

mm

D.O.A. _____

26/12/22

D.O.I. _____

24/2/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S - RS. \$

Fees

Others

Add Fee: ☐

Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 1/s \$1,500.00)

VEHICLE NO: SMC644Y

MODEL: TOYOTA ALTIS

CHASSIS NO: MR053REH604583449

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
FRONT BUMPER		<i>Bulldo</i> \$ 500.00 ✓
FRONT BUMPER LOWER GRILLE		\$ <i>Pn</i> 300.00 X
FRONT GRILLE		\$ <i>Pn</i> 350.00 X
FRONT GRILLE EMBLEM		\$ <i>Pn</i> 100.00 X
FRONT REINFORCEMENT		\$ <i>Pn</i> 350.00 X
HEADLAMP LHS		<i>W</i> \$ 1,250.00 ✓
	25%	\$ 2,850.00
		\$ 712.50
		\$ 2,137.50
<u>SPECIAL NETT ITEMS</u>		
FRONT BUMPER CLIPS		\$ <i>W</i> 60.00 ✓
	Total	\$ 60.00
	TOTAL PARTS	\$ 2,197.50

NOT Withain
 61 Day \$1500/-
 Return After Part
 2 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,000.00	2000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,000.00	2200
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	200
4	To provide anti-rust treatment on affected areas	\$ 100.00	X
	Labour Total :	\$ 2,200.00	
	TOTAL (PARTS & LABOUR):	\$ 4,397.50	

SUPPLEMENTARY PARTS

VEHICLE NO: SMC644Y

MODEL: TOYOTA ALTIS

CHASSIS NO: MR053REH604583449

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>		
FRONT REINFORCEMENT SPONGE		<i>CM</i> \$ 100.00 ✓
	25%	\$ 100.00
		\$ 25.00
		\$ 75.00
<u>SPECIAL NETT ITEMS</u>		
	TOTAL:	\$ -
	TOTAL PARTS	\$ 75.00

<u>LABOUR</u>		
	TOTAL:	\$ -
	(LABOUR + PARTS) TOTAL:	\$ 75.00