



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23002063/Rvy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	29/03/2023
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 220D	Veh. Inspected	SLT 4948S
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/009	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	24/02/2023
2. Vehicle Particulars & Condition			
Make & Model	MAZDA5 WAGON 2.0 AT S/R	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6CW1071H0126447	Colour	BLUE
Odometer	347599 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R16	WEST LAKE	6 mm
L/H Front Tyre	205/55R16	WEST LAKE	6 mm
R/H Rear Tyre	205/55R16	WEST LAKE	6 mm
L/H Rear Tyre	205/55R16	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/02/2023	Inspection Date	27/02/2023
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD		
	74 Kian Teck Road		
	Singapore 628800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	