

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0192/2023/EQ
DATE : 20-Feb-23
WIP : 63896

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS RACHEL KHOO PENG PEI
ADDRESS : 21 TAN KIM CHENG ROAD
#05-23
SINGAPORE 266621
TELEPHONE : HP +65 92989465
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800098404-04
VEHICLE NO : **SMD 6647 U**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 30/8/2018
ENGINE NO : CHZ 922218
CHASSIS NO : WAUZZZ8V8J1062613
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Feb-23
PLACE OF ACCIDENT : ALONG QUEENS ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 6647 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND FRONT PARKING AID.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 1,700.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,702.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 6647 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Reh d</i>	1	\$ 2,576.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 207.00	x
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>LH Reh d</i>	1	\$ 46.00 23	23
4	FRONT BUMPER CLOSING ELEMENT - LH ?	1	\$ 337.00	?
5	FRONT BUMPER TRIM COVER - LH <i>new</i>	1	\$ 193.00	x
6	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 222.00	x
7	FRONT FENDER - LH <i>Dented</i>	1	\$ 1,012.00	✓
8	FRONT FENDER RIVET ?	5	\$ 20.00	?
9	FRONT FENDER BRACKET - LH ?	1	\$ 57.00	?
10	FRONT FENDER BRACE ?	1	\$ 114.00	?
11	FRONT WHEEL HOUSING LINER - LH <i>ton</i>	1	\$ 198.00	✓
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	1	\$ 99.00	?
13	HEADLIGHT - LH ?	1	\$ 6,232.00	?
14	HEADLIGHT HEAT SINK - LH <i>new</i>	1	\$ 868.00	x
15	SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 12,481.00	
TOTAL LABOUR CHARGES		:	\$ 4,702.00	
GRAND TOTAL		:	\$ 17,183.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *23/02/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT