

Name & Address:

Motor Claims Department

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Vehicle No:

SFA999S

Brand & Model:

Cayenne

Chassis/VIN No:

WP1ZZZ9YZLDA03130

Date:

21-Feb-23

Franchise:

PORSCHE

Contact Person (Eurokars):

DEREK

Contact No (Eurokars):

6331 0684

Type of Claim:

OWN DAMAGE

YEAR MODEL:

28/02/2020

WIP#:

42780
PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>scd /</i>	P9Y0-807-217- -G2X	1		-	\$ 2,531.20
2	TOWING COVER LH <i>X</i>	P9Y0-807-155- -G2X	1		-	\$ 112.60
3	TOWING COVER RH <i>X</i>	P9Y0-807-156- -G2X	1		-	\$ 112.60
4	EXPANDER NUT <i>n /</i>	PWHT-004-935- -	2		-	\$ 3.40
5	CLAMP <i>n /</i>	P9Y0-423-337- -	4		-	\$ 20.00
6	RIVET <i>n /</i>	PN -038-501-2 -	8		-	\$ 15.20
7	GRILLE TRIM RH <i>X</i>	P9Y0-807-686- -OK1	1		-	\$ 165.20
8	FRONT BUMPER LOWER SPOILER <i>scd /</i>	P9Y0-807-061- -OK1	1		-	\$ 1,072.60
9	GRILLE RH <i>?</i>	P9Y0-807-682- -OK1	1		-	\$ 199.50
10	BUMPER GUIDE RH <i>?</i>	P9Y0-807-178-C -	1		-	\$ 100.80
11	EXPANDER NUT <i>n /</i>	PWHT-004-935- -	8		-	\$ 13.60
12	BLIND RIVET <i>n /</i>	PN -903-463-01-	10		-	\$ 18.00
13	BUMPER AIRDUCT RH <i>X</i>	P9Y0-807-958-C -OK1	1		-	\$ 79.30
14	HEADLIGHT BRACKET RH <i>X</i>	P9Y0-807-572-B -	1		-	\$ 80.60
15	BUMPER RETAINER RH <i>?</i>	P9Y0-807-050-F -	1		-	\$ 87.40
16	FRONT SUBFRAME <i>?</i>	PPAB-399-315- -	1		-	\$ 4,374.90
17	REINFORCEMENT PLATE FOR SUBFRAME <i>?</i>	PPAB-399-345-B -	1		-	\$ 671.10
18	COMBINATION SCREW <i>?</i>	PPAF-911-511- -	4		-	\$ 38.00
19	COMBINATION SCREW <i>?</i>	PPAF-005-372- -	2		-	\$ 29.40
20	SQUARE NUT <i>?</i>	PWHT-002-305- -	4		-	\$ 23.20
21	HEXAGON SOCKET HEAD BOLT <i>?</i>	PN -912-088-02-	3		-	\$ 7.80
22	HEXAGON-HEAD BOLT <i>?</i>	PN -106-532-01-	3		-	\$ 9.30
23	DOUBLE SCREW <i>?</i>	PN -911-251-02-	1		-	\$ 9.00
24	HEXAGON-HEAD BOLT <i>?</i>	PPAF-912-379-01-	4		-	\$ 88.40
25	HEXAGON-HEAD BOLT <i>?</i>	PPAF-911-843-01-	4		-	\$ 92.80
26	WISHBONE UPPER FRONT RH <i>?</i>	P958-407-506-C -	1		-	\$ 570.50
27	WISHBONE UPPER REAR RH <i>?</i>	P958-407-510-C -	1		-	\$ 570.50
28	HEXAGON-HEAD BOLT <i>?</i>	PPAF-912-216-01-	2		-	\$ 25.80
29	GUIDE ROD RH <i>?</i>	PPAB-407-694- -	1		-	\$ 1,156.20
30	TRACK CONTROL ARM RH <i>?</i>	PPAB-407-152- -	1		-	\$ 762.60
31	12 POINT SOCKET <i>?</i>	PPAF-007-028- -	2		-	\$ 35.60
32	HEXAGON NUT <i>?</i>	PPAF-001-987- -	2		-	\$ 18.60
33	HEXAGON BOLT <i>?</i>	PPAF-108-176-01-	2		-	\$ 44.20
34	HEXAGON-HEAD BOLT <i>?</i>	PWHT-006-151- -	2		-	\$ 23.40
35	SELF-LEVELLING SENSOR RH <i>?</i>	PPAB-941-286-01-	1		-	\$ 509.10
36	HEXAGON NUT <i>?</i>	PPAF-015-082- -	2		-	\$ 3.20
37	HEXAGON-HEAD BOLT <i>?</i>	PN -909-995-02-	2		-	\$ 4.40

REPAIR ESTIMATE

38	FRONT WHEEL CARRIER RH ?	P9Y0-407-246- -	1	-	\$ 1,700.20
39	ANGULAR-CONTACT BEARING FRONT RH ?	P958-407-625-D -	1	-	\$ 529.60
40	WHEEL HUB FRONT RH ?	P958-501-651- -	1	-	\$ 750.50
41	MULTIPLE-TOOTH SCREW ?	P958-006-966- -	4	-	\$ 34.80
42	POT ?	P958-407-689-C -	1	-	\$ 260.90
43	HEXAGON-HEAD BOLT ?	PN -102-415-07-	2	-	\$ 16.20
44	HEXAGON-HEAD BOLT ?	PWHT-006-151- -	2	-	\$ 23.40
45	HEXAGON FLANGE SCREW ?	PWHT-006-542- -	2	-	\$ 28.40
46	HEXAGON NUT ?	PN -102-723-02-	2	-	\$ 7.40
47	SPEED SENSOR ?	P958-927-807- -	1	-	\$ 325.00
48	PN -014-740-11-/PAN-HEAD SCREW ?	PN -911-454-01-	2	-	\$ 3.60
49	ACCELERATION SENSOR ?	P971-907-656- -	1	-	\$ 162.50
50	HEXAGON-HEAD BOLT ?	PPAF-100-636-04-	2	-	\$ 6.60
51	HEXAGON-HEAD BOLT ?	PPAB-407-643- -	2	-	\$ 65.00
52	FRONT SHOCK ABSORBER RH ?	PPAB-413-031- -	1	-	\$ 1,584.00
53	FRONT SHOCK ABSORBER MOUNTING RH ?	PPAB-412-377-00-	1	-	\$ 228.90
54	CAP ?	P958-412-375-A -	1	-	\$ 28.00
55	(AJ06) NUT HEXAGON, WISHBONE ?	PPAF-104-029- -	2	-	\$ 18.60
56	RUBBER STOP ?	P958-412-131-00-	1	-	\$ 122.50
57	BOOT ?	PPAB-412-137-00-	1	-	\$ 11.50
58	PROTECTION CAP ?	PPAB-412-127-00-	1	-	\$ 26.60
59	CONCAVE SUPPORT ?	P958-412-109-A -	1	-	\$ 46.70
60	CONCAVE WASHER ?	P958-412-103-A -	1	-	\$ 60.00
61	SHOCK ABSORBER BRACKET RH ?	P958-413-038-H -	1	-	\$ 786.40
62	COMBINATION SCREW ?	PN -102-722-02-	2	-	\$ 24.00
63	HEXAGON NUT ?	PN -101-064-02-	2	-	\$ 7.40
64	HEXAGON BOLT WITH WASHER ?	PPAF-912-603- -	4	-	\$ 34.80
65	SHOCK ABSORBER SPOILER RH ?	P9Y0-615-448-C -	1	-	\$ 102.00
66	TIE-WRAP ?	P9A7-008-379-00-	1	-	\$ 9.90
67	HEXAGON-HEAD BOLT ?	PN -107-847-02-	2	-	\$ 19.80
68	HEXAGON NUT ?	PPAF-001-987- -	2	-	\$ 18.60
69	CLAMP ?	PPAB-411-336-01-	2	-	\$ 143.80
70	HEXAGON NUT ?	PN -102-613-11-	4	-	\$ 13.20
71	STABILIZER LINK RH ?	PPAB-411-317-A -	1	-	\$ 179.70
72	12 POINT SOCKET ?	PWHT-007-061- -	1	-	\$ 10.30
73	HEXAGON NUT SCREW, WISHBONE UPPER ?	PPAF-102-861- -	1	-	\$ 4.80
74	12 POINT SOCKET ?	PWHT-006-917- -	1	-	\$ 7.00
75	HEXAGON NUT SCREW, WISHBONE UPPER ?	PPAF-102-861- -	1	-	\$ 4.80
76	STEERING GEAR ?	PPAB-423-055-E -	1	-	\$ 8,134.40
77	TRACK ROD RH ?	P9Y0-423-811-B -	1	-	\$ 704.50
78	HEXAGON FLAT NUT ?	PN -011-164-17-	2	-	\$ 8.60
79	HEXAGON-HEAD BOLT ?	PWHT-006-151- -	2	-	\$ 23.40
80	HEXAGON HEAD BOLT (COMBI) ?	PWHT-006-662- -	2	-	\$ 48.20
81	SQUARE NUT ?	PWHT-002-305- -	2	-	\$ 11.60
82	MULTIPLE-TOOTH SCREW ?	PN -105-184-05-	1	-	\$ 5.40
83					\$ -

Sub-Total (Parts Price) \$ 30,023.50

REPAIR ESTIMATE

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560	\$ 3,000.00
2	TO RESPRAY FRONT BUMPER, FRT RIM RH	1300	\$ 1,800.00
3	TO REMOVE & REPLACE THE FRONT UNDER CARRIAGE RH INCLUDING SUBFRAME & STEERING GEAR.	nett ?	\$ 3,120.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	nett	\$ 680.00
5	TO TRANSFER THE FRONT BUMPER SENSORS.	nett	\$ 150 300.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
8	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice</i>	nett	\$? 300.00
9	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time: *24/02/23 @ 1710* Repair Days: *6 days p/p* Excess: *2500*

Surveyor Remarks: *Rasul - 4p 90010068*

EXCESS: TBA

REVERT

Pass before paint

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 11,000.00

	REVISED	PRICE
Parts Price	\$ -	\$ 30,023.50
Labour Price	\$ -	\$ 11,000.00
Total (Initial Estimate)	\$ -	\$ 41,023.50
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 41,023.50
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 41,023.50
GST 8%	\$ -	\$ 3,281.88
GRAND TOTAL	\$ -	\$ 44,305.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: