

ASS. REC. BY: JB

REF: CS/CT123002068/RVP3

639T

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____


OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFA 999Sat Workshop m/s TRANS EUROKARSof 27A, PenangInsured: CTIPolicy No. DMPCSNW00055842201Claims No. SNM23D201151/C01/TAYHPSum Insured: _____ Excess: 2500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 392K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFA 999S Yr Regn: 2020 / PEBType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: PORSCHE CAYENNE E3 TYPE c.c. 2995Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 75895 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP122294260403130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt orBrake: in order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 255/55R19R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/02/23

Survey held at

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

O/S Fit
The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 24/02/23

Date / Time

Action / Instruction

REPAIR LIMIT - 262K

19/6/23 Final fig \$26,474.20 confirmed by email (Red 14,975.90, 36%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/6/23-typistDays Of Repair: 6

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Rep. Format: MerimenLump Sum / L.B. / \$26,474.20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/02/2023 13:28 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	12/02/2023 11:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TOH TUCK TERRACE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFA999S
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WONG CHOK YIN
NRIC No	SXXXX639I
Email Address	V2INTERNATIONAL@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-93801611
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Porsche
Model	Cayenne
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2995

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	-

DRIVER

Name of Driver	WONG CHOK YIN
NRIC No	SXXXX639I
Date Of Birth	02/11/1959
Occupation	Indoor

Date Of Driving Pass	24/05/1978
Driving experience	44 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93801611
Alt. Phone Number	-
Email Address	V2INTERNATIONAL@YAHOO.COM.SG
Address	NO 7 TOH TUCK TERRACE S596643
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGK1623E
Vehicle Manufacturer	Honda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Order to sketch plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Order to attach


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:



I was travelling along Toh Tuck Terrace.

As I was turning into my house, vehicle (B) decided to overtake my car (A).

As a result, vehicle (B) hit onto the Front Right portion of my car (A) as he was trying to overtake by going against traffic while on the other lane.

My car (A) was badly damaged to the point where I could not drive anymore.

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Type of Claim:

YEAR MODEL:

OWN DAMAGE

28/02/2020

Vehicle No:

SFA999S

Brand & Model:

Cayenne

Chassis/VIN No:

WP1ZZZ9YZLDA03130

WIP#:

42780

Date:

21-Feb-23

Franchise:

PORSCHE

Contact Person (Eurokars):

DEREK

Contact No (Eurokars):

6331 0684

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>scu /</i>	P9Y0-807-217- -G2X	1		-	\$ 2,531.20
2	TOWING COVER LH <i>Xan</i>	P9Y0-807-155- -G2X	1		-	\$ 112.60
3	TOWING COVER RH <i>Xan</i>	P9Y0-807-156- -G2X	1		-	\$ 112.60
4	EXPANDER NUT <i>n /</i>	PWHT-004-935- -	2		-	\$ 3.40
5	CLAMP <i>n /</i>	P9Y0-423-337- -	4		-	\$ 20.00
6	RIVET <i>n /</i>	PN -038-501-2 -	8		-	\$ 15.20
7	GRILLE TRIM RH <i>Xan</i>	P9Y0-807-686- -OK1	1		-	\$ 165.20
8	FRONT BUMPER LOWER SPOILER <i>scu /</i>	P9Y0-807-061- -OK1	1		-	\$ 1,072.60
9	GRILLE RH <i>? Xan</i>	P9Y0-807-682- -OK1	1		-	\$ 199.50
10	BUMPER GUIDE RH <i>? Xan</i>	P9Y0-807-178-C -	1		-	\$ 100.80
11	EXPANDER NUT <i>n /</i>	PWHT-004-935- -	8		-	\$ 13.60
12	BLIND RIVET <i>n /</i>	PN -903-463-01-	10		-	\$ 18.00
13	BUMPER AIRDUCT RH <i>Xan</i>	P9Y0-807-958-C -OK1	1		-	\$ 79.30
14	HEADLIGHT BRACKET RH <i>Xan</i>	P9Y0-807-572-B -	1		-	\$ 80.60
15	BUMPER RETAINER RH <i>? Xan</i>	P9Y0-807-050-F -	1		-	\$ 87.40
16	FRONT SUBFRAME <i>? Xan</i>	PPAB-399-315- -	1		-	\$ 4,374.90
17	REINFORCEMENT PLATE FOR SUBFRAME <i>? Xan</i>	PPAB-399-345-B -	1		-	\$ 671.10
18	COMBINATION SCREW <i>? nu /</i>	PPAF-911-511- -	4		-	\$ 38.00
19	COMBINATION SCREW <i>? nu /</i>	PPAF-005-372- -	2		-	\$ 29.40
20	SQUARE NUT <i>? nu /</i>	PWHT-002-305- -	4		-	\$ 23.20
21	HEXAGON SOCKET HEAD BOLT <i>? nu /</i>	PN -912-088-02-	3		-	\$ 7.80
22	HEXAGON-HEAD BOLT <i>? nu / X nn</i>	PN -106-532-01-	3		-	\$ 9.30
23	DOUBLE SCREW <i>? nu /</i>	PN -911-251-02-	1		-	\$ 9.00
24	HEXAGON-HEAD BOLT <i>? nu /</i>	PPAF-912-379-01-	4		-	\$ 88.40
25	HEXAGON-HEAD BOLT <i>? nu /</i>	PPAF-911-843-01-	4		-	\$ 92.80
26	WISHBONE UPPER FRONT RH <i>? Xan</i>	P958-407-506-C -	1		-	\$ 570.50
27	WISHBONE UPPER REAR RH <i>? Xan</i>	P958-407-510-C -	1		-	\$ 570.50
28	HEXAGON-HEAD BOLT <i>? Xan</i>	PPAF-912-216-01-	1		-	\$ 25.80
29	GUIDE ROD RH <i>? bt /</i>	PPAB-407-694- -	1		-	\$ 1,156.20
30	TRACK CONTROL ARM RH <i>? bt /</i>	PPAB-407-152- -	1		-	\$ 762.60
31	12 POINT SOCKET <i>? nu /</i>	PPAF-007-028- -	1		-	\$ 35.60
32	HEXAGON NUT <i>? nu /</i>	PPAF-001-987- -	1		-	\$ 18.60
33	HEXAGON BOLT <i>? nu /</i>	PPAF-108-176-01-	1		-	\$ 44.20
34	HEXAGON-HEAD BOLT <i>? nu /</i>	PWHT-006-151- -	1		-	\$ 23.40
35	SELF-LEVELLING SENSOR RH <i>? Xan</i>	PPAB-941-286-01-	1		-	\$ 509.10
36	HEXAGON NUT <i>? Xan</i>	PPAF-015-082- -	1		-	\$ 3.20
37	HEXAGON-HEAD BOLT <i>? nu /</i>	PN -909-995-02-	1		-	\$ 4.40

38	FRONT WHEEL CARRIER RH ? bt /	P9Y0-407-246- -	2	-	\$	1,700.20
39	ANGULAR-CONTACT BEARING FRONT RH ? new	P958-407-625-D -	2	-	\$	529.60
40	WHEEL HUB FRONT RH ? bt /	P958-501-651- -	2	-	\$	750.50
41	MULTIPLE-TOOTH SCREW ? new	P958-006-966- -	4	-	\$	34.80
42	POT ? bt /	P958-407-689-C -	2	-	\$	260.90
43	HEXAGON-HEAD BOLT ? new	PN -102-415-07-	2	-	\$	16.20
44	HEXAGON-HEAD BOLT ? new	PWHT-006-151- -	2	-	\$	23.40
45	HEXAGON FLANGE SCREW ? new	PWHT-006-542- -	2	-	\$	28.40
46	HEXAGON NUT ? new	PN -102-723-02-	2	-	\$	7.40
47	SPEED SENSOR ? Xan	P958-927-807- -	2	-	\$	325.00
48	PN -014-740-11-/PAN-HEAD SCREW ? Xan	PN -911-454-01-	2	-	\$	3.60
49	ACCELERATION SENSOR ? Xan	P971-907-656- -	2	-	\$	162.50
50	HEXAGON-HEAD BOLT ? new	PPAF-100-636-04-	2	-	\$	6.60
51	HEXAGON-HEAD BOLT ? new	PPAB-407-643- -	2	-	\$	65.00
52	FRONT SHOCK ABSORBER RH ? new	PPAB-413-031- -	2	-	\$	1,584.00
53	FRONT SHOCK ABSORBER MOUNTING RH ? new	PPAB-412-377-00-	2	-	\$	228.90
54	CAP ? new	P958-412-375-A -	2	-	\$	28.00
55	(AJ06) NUT HEXAGON, WISHBONE ? bt /	PPAF-104-029- -	2	-	\$	18.60
56	RUBBER STOP ? new	P958-412-131-00-	2	-	\$	122.50
57	BOOT ? new	PPAB-412-137-00-	2	-	\$	11.50
58	PROTECTION CAP ? new	PPAB-412-127-00-	2	-	\$	26.60
59	CONCAVE SUPPORT ? new	P958-412-109-A -	2	-	\$	46.70
60	CONCAVE WASHER ? new	P958-412-103-A -	2	-	\$	60.00
61	SHOCK ABSORBER BRACKET RH ? new	P958-413-038-H -	2	-	\$	786.40
62	COMBINATION SCREW ? new	PN -102-722-02-	2	-	\$	24.00
63	HEXAGON NUT ? new	PN -101-064-02-	2	-	\$	7.40
64	HEXAGON BOLT WITH WASHER ? new	PPAF-912-603- -	4	-	\$	34.80
65	SHOCK ABSORBER SPOILER RH ? Xan	P9Y0-615-448-C -	2	-	\$	102.00
66	TIE-WRAP ? new	P9A7-008-379-00-	2	-	\$	9.90
67	HEXAGON-HEAD BOLT ? new	PN -107-847-02-	2	-	\$	19.80
68	HEXAGON NUT ? new	PPAF-001-987- -	2	-	\$	18.60
69	CLAMP ? Xan	PPAB-411-336-01-	2	-	\$	143.80
70	HEXAGON NUT ? Xan	PN -102-613-11-	4	-	\$	13.20
71	STABILIZER LINK RH ? bt /	PPAB-411-317-A -	2	-	\$	179.70
72	12 POINT SOCKET ? new	PWHT-007-061- -	2	-	\$	10.30
73	HEXAGON NUT SCREW, WISHBONE UPPER ? new	PPAF-102-861- -	2	-	\$	4.80
74	12 POINT SOCKET ? new	PWHT-006-917- -	2	-	\$	7.00
75	HEXAGON NUT SCREW, WISHBONE UPPER ? Xan	PPAF-102-861- -	2	-	\$	4.80
76	STEERING GEAR ? bt /	PPAB-423-055-E -	2	-	\$	8,134.40
77	TRACK ROD RH ? bt /	P9Y0-423-811-B -	2	-	\$	704.50
78	HEXAGON FLAT NUT ? Xan	PN -011-164-17-	2	-	\$	8.60
79	HEXAGON-HEAD BOLT ? new	PWHT-006-151- -	2	-	\$	23.40
80	HEXAGON HEAD BOLT (COMBI) ? new	PWHT-006-662- -	2	-	\$	48.20
81	SQUARE NUT ? new	PWHT-002-305- -	2	-	\$	11.60
82	MULTIPLE-TOOTH SCREW ? new	PN -105-184-05-	2	-	\$	5.40
83					\$	-

Sub-Total (Parts Price) \$ - \$ 30,023.50

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560	\$ 3,800.00
2	TO RESPRAY FRONT BUMPER, FRT RIM RH	1300	\$ 1,800.00
3	TO REMOVE & REPLACE THE FRONT UNDER CARRIAGE RH INCLUDING SUBFRAME & STEERING GEAR.	Xm nett ?	\$ 3,120.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	nett	\$ 680.00
5	TO TRANSFER THE FRONT BUMPER SENSORS.	nett	\$ 150 308.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150 258.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
8	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice</i>	Xm nett ?	\$ 300.00
9	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time: *24/02/23 @ 1710* Repair Days: *6 days p/p* Excess: *2500*

Surveyor Remarks: *Rasul - 4p 90010068*

EXCESS: TBA

Revert

Body before paint

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 11,000.00

	REVISED	PRICE
Parts Price	\$ -	\$ 30,023.50
Labour Price	\$ -	\$ 11,000.00
Total (Initial Estimate)	\$ -	\$ 41,023.50
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 41,023.50
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 41,023.50
GST 8%	\$ -	\$ 3,281.88
GRAND TOTAL	\$ -	\$ 44,305.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Email/Fax No:

Contact No:

Type of Claim:

OWN DAMAGE

YEAR MODEL:

28/02/2020

Vehicle No:

SFA999S

Brand & Model:

Cayenne

Chassis/VIN No:

WP1ZZZ9YZLDA03130

WIP#:

42780

Date:

26-Apr-23

Franchise:

PORSCHÉ

Contact Person (Eurokars):

DEREK

Contact No (Eurokars):

6331 0684

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER	P9Y0-807-217- -G2X	1	A	\$ 2,531.20	\$ 2,531.20
2	TOWING COVER LH	P9Y0-807-155- -G2X	1		\$ -	\$ 112.60
3	TOWING COVER RH	P9Y0-807-156- -G2X	1		\$ -	\$ 112.60
4	EXPANDER NUT	PWHT-004-935- -	2	A	\$ 3.40	\$ 3.40
5	CLAMP	P9Y0-423-337- -	4	A	\$ 20.00	\$ 20.00
6	RIVET	PN -038-501-2 -	8	A	\$ 15.20	\$ 15.20
7	GRILLE TRIM RH	P9Y0-807-686- -OK1	1		\$ -	\$ 165.20
8	FRONT BUMPER LOWER SPOILER	P9Y0-807-061- -OK1	1	A	\$ 1,072.60	\$ 1,072.60
9	GRILLE RH	P9Y0-807-682- -OK1	1		\$ -	\$ 199.50
10	BUMPER GUIDE RH	P9Y0-807-178-C -	1		\$ -	\$ 100.80
11	EXPANDER NUT	PWHT-004-935- -	8	A	\$ 13.60	\$ 13.60
12	BLIND RIVET	PN -903-463-01-	10	A	\$ 18.00	\$ 18.00
13	BUMPER AIRDUCT RH	P9Y0-807-958-C -OK1	1		\$ -	\$ 79.30
14	HEADLIGHT BRACKET RH	P9Y0-807-572-B -	1		\$ -	\$ 80.60
15	BUMPER RETAINER RH	P9Y0-807-050-F -	1		\$ -	\$ 87.40
16	FRONT SUBFRAME	PPAB-399-315- -	1		\$ -	\$ 4,374.90
17	REINFORCEMENT PLATE FOR SUBFRAME	PPAB-399-345-B -	1		\$ -	\$ 671.10
18	COMBINATION SCREW	PPAF-911-511- -	4	A	\$ 38.00	\$ 38.00
19	COMBINATION SCREW	PPAF-005-372- -	2	A	\$ 29.40	\$ 29.40
20	SQUARE NUT	PWHT-002-305- -	4	A	\$ 23.20	\$ 23.20
21	HEXAGON SOCKET HEAD BOLT	PN -912-088-02-	3	A	\$ 7.80	\$ 7.80
22	HEXAGON-HEAD BOLT	PN -106-532-01-	3		\$ -	\$ 9.30
23	DOUBLE SCREW	PN -911-251-02-	1	A	\$ 9.00	\$ 9.00
24	HEXAGON-HEAD BOLT	PPAF-912-379-01-	4	A	\$ 88.40	\$ 88.40
25	HEXAGON-HEAD BOLT	PPAF-911-843-01-	4	A	\$ 92.80	\$ 92.80
26	WISHBONE UPPER FRONT RH	P958-407-506-C -	1		\$ -	\$ 570.50
27	WISHBONE UPPER REAR RH	P958-407-510-C -	1		\$ -	\$ 570.50
28	HEXAGON-HEAD BOLT	PPAF-912-216-01-	2		\$ -	\$ 25.80
29	GUIDE ROD RH	PPAB-407-694- -	1	A	\$ 1,156.20	\$ 1,156.20
30	TRACK CONTROL ARM RH	PPAB-407-152- -	1	A	\$ 762.60	\$ 762.60
31	12 POINT SOCKET	PPAF-007-028- -	2	A	\$ 35.60	\$ 35.60
32	HEXAGON NUT	PPAF-001-987- -	2	A	\$ 18.60	\$ 18.60

33	HEXAGON BOLT	PPAF-108-176-01-	2	A	\$	44.20	\$	44.20
34	HEXAGON-HEAD BOLT	PWHT-006-151- -	2	A	\$	23.40	\$	23.40
35	SELF-LEVELLING SENSOR RH	PPAB-941-286-01-	1		\$	-	\$	509.10
36	HEXAGON NUT	PPAF-015-082- -	2		\$	-	\$	3.20
37	HEXAGON-HEAD BOLT	PN -909-995-02-	2	A	\$	4.40	\$	4.40
38	FRONT WHEEL CARRIER RH	P9Y0-407-246- -	1	A	\$	1,700.20	\$	1,700.20
39	ANGULAR-CONTACT BEARING FRONT RH	P958-407-625-D -	1	A	\$	529.60	\$	529.60
40	WHEEL HUB FRONT RH	P958-501-651- -	1	A	\$	750.50	\$	750.50
41	MULTIPLE-TOOTH SCREW	P958-006-966- -	4	A	\$	34.80	\$	34.80
42	POT	P958-407-689-C -	1	A	\$	260.90	\$	260.90
43	HEXAGON-HEAD BOLT	PN -102-415-07-	2	A	\$	16.20	\$	16.20
44	HEXAGON-HEAD BOLT	PWHT-006-151- -	2	A	\$	23.40	\$	23.40
45	HEXAGON FLANGE SCREW	PWHT-006-542- -	2	A	\$	28.40	\$	28.40
46	HEXAGON NUT	PN -102-723-02-	2	A	\$	7.40	\$	7.40
47	SPEED SENSOR	P958-927-807- -	1		\$	-	\$	325.00
48	PN -014-740-11-/PAN-HEAD SCREW	PN -911-454-01-	2		\$	-	\$	3.60
49	ACCELERATION SENSOR	P971-907-656- -	1		\$	-	\$	162.50
50	HEXAGON-HEAD BOLT	PPAF-100-636-04-	2	A	\$	6.60	\$	6.60
51	HEXAGON-HEAD BOLT	PPAB-407-643- -	2	A	\$	65.00	\$	65.00
52	FRONT SHOCK ABSORBER RH	PPAB-413-031- -	1	A	\$	1,584.00	\$	1,584.00
53	FRONT SHOCK ABSORBER MOUNTING RH	PPAB-412-377-00-	1	A	\$	228.90	\$	228.90
54	CAP	P958-412-375-A -	1	A	\$	28.00	\$	28.00
55	(AJ06) NUT HEXAGON, WISHBONE	PPAF-104-029- -	2	A	\$	18.60	\$	18.60
56	RUBBER STOP	P958-412-131-00-	1	A	\$	122.50	\$	122.50
57	BOOT	PPAB-412-137-00-	1	A	\$	11.50	\$	11.50
58	PROTECTION CAP	PPAB-412-127-00-	1	A	\$	26.60	\$	26.60
59	CONCAVE SUPPORT	P958-412-109-A -	1	A	\$	46.70	\$	46.70
60	CONCAVE WASHER	P958-412-103-A -	1	A	\$	60.00	\$	60.00
61	SHOCK ABSORBER BRACKET RH	P958-413-038-H -	1	A	\$	786.40	\$	786.40
62	COMBINATION SCREW	PN -102-722-02-	2	A	\$	24.00	\$	24.00
63	HEXAGON NUT	PN -101-064-02-	2	A	\$	7.40	\$	7.40
64	HEXAGON BOLT WITH WASHER	PPAF-912-603- -	4	A	\$	34.80	\$	34.80
65	SHOCK ABSORBER SPOILER RH	P9Y0-615-448-C -	1		\$	-	\$	102.00
66	TIE-WRAP	P9A7-008-379-00-	1	A	\$	9.90	\$	9.90
67	HEXAGON-HEAD BOLT	PN -107-847-02-	2	A	\$	19.80	\$	19.80
68	HEXAGON NUT	PPAF-001-987- -	2	A	\$	18.60	\$	18.60
69	CLAMP	PPAB-411-336-01-	2		\$	-	\$	143.80
70	HEXAGON NUT	PN -102-613-11-	4		\$	-	\$	13.20
71	STABILIZER LINK RH	PPAB-411-317-A -	1	A	\$	179.70	\$	179.70
72	12 POINT SOCKET	PWHT-007-061- -	1	A	\$	10.30	\$	10.30
73	HEXAGON NUT SCREW, WISHBONE UPPER	PPAF-102-861- -	1	A	\$	4.80	\$	4.80
74	12 POINT SOCKET	PWHT-006-917- -	1	A	\$	7.00	\$	7.00
75	HEXAGON NUT SCREW, WISHBONE UPPER	PPAF-102-861- -	1		\$	-	\$	4.80
76	STEERING GEAR	PPAB-423-055-E -	1	A	\$	8,134.40	\$	8,134.40

77	TRACK ROD RH	P9Y0-423-811-B -	1	A	\$	704.50	\$	704.50
78	HEXAGON FLAT NUT	PN -011-164-17-	2		\$	-	\$	8.60
79	HEXAGON-HEAD BOLT	PWHT-006-151- -	2	A	\$	23.40	\$	23.40
80	HEXAGON HEAD BOLT (COMBI)	PWHT-006-662- -	2	A	\$	48.20	\$	48.20
81	SQUARE NUT	PWHT-002-305- -	2	A	\$	11.60	\$	11.60
82	MULTIPLE-TOOTH SCREW	PN -105-184-05-	1	A	\$	5.40	\$	5.40
83	WHEEL COVER BLACK MAT <i>dur</i>	P9Y0-853-718-J-OK1	1	A	\$	349.90	\$	349.90 (A)
84	COVER PLATE <i>bt</i>	PPAB-615-312-01	1	A	\$	76.70	\$	76.70 (A)

Sub-Total (Parts Price) \$ 22,014.20 \$ 30,450.10

LABOUR / SERVICES CHARGES						REVISED	PRICE
NO	DESCRIPTION						
1	TO REMOVE /REPLACE FRT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.					\$ 1,560.00	\$ 3,900.00
2	TO RESPRAY FRONT BUMPER, FRT RIM RH					\$ 1,300.00	\$ 1,800.00
3	TO REMOVE & REPLACE THE FRONT UNDER CARRIAGE RH INCLUDING SUBFRAME & STEERING GEAR.					\$ -	\$ 3,120.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.					\$ 680.00	\$ 680.00
5	TO TRANSFER THE FRONT BUMPER SENSORS.					\$ 150.00	\$ 300.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.					\$ 150.00	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					\$ 600.00	\$ 600.00
8	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.					\$ -	\$ 300.00
9	SUNDRIES.					\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days: 6	Excess: \$2500
---------------------	----------------	----------------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$	4,460.00	\$	11,000.00
		REVISED		PRICE
Parts Price	\$	22,014.20	\$	30,450.10
Labour Price	\$	4,460.00	\$	11,000.00
Total (Initial Estimate)	\$	26,474.20	\$	41,450.10
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	26,474.20	\$	41,450.10
Less Excess	\$	2,500.00	\$	2,500.00
TOTAL (After Excess)	\$	23,974.20	\$	38,950.10
GST 8%	\$	1,917.94	\$	3,116.01
GRAND TOTAL	\$	25,892.14	\$	42,066.11