# Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

> Paya Ubi Industrial Park Singapore 408933

Attn: 27 Feb 2023 Noor Amran, Noor Yussyuhaila Date:

## **Preliminary Advice**

Vehicle No : SJX6611C **Accident Date** : 29/12/2022 Policy No. Make : AUDI A3 : 1900164546 Assignment Date : 24/02/2023 Excess : S\$0.00 Date of Inspection : 24/02/2023 Est. Duration of Repair : 3

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

SINGAPORE 408699

55 UBI ROAD 1

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,295.00
Revised Amount	:S\$	3,839.00
Check Items (Estimated)	:S\$	300.00
Total	:S\$	4,139.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 100,000.00 COE / PARF Rebate :S\$ 38,102.00

Salvage Value :S\$

Margin for Repair :S\$ 61,898.00

### Remarks

( x )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kind	dly
	let us have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x)Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.