

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1182/2022/EQ
DATE : 4-Jan-23
WIP : 57054

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR DESMOND LIM TENG KHENG
ADDRESS : BLK 555 JURONG WEST STREET 42
#09-367
SINGAPORE 640555
TELEPHONE : HP +65 91147348
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900164546-01
VEHICLE NO : **SJX 6611 C**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 25/9/2019
ENGINE NO : CHZ C31647
CHASSIS NO : WAUZZZ8V6KA103659
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Dec-22
PLACE OF ACCIDENT : CORPORATION ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJX 6611 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00 ✓	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00 ✓ 500 ✓	✓
3	TO RESPRAY REAR BUMPER.	\$	900.00 ✓ 550 ✓	✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$	2,422.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 6611 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dehid</i>	1	\$ 2,317.00	<i>✓ 1853.60</i>
2	REAR BUMPER FIXING PARTS	1	\$ 201.00	<i>X</i>
3	REAR WHEEL HOUSING LINER ADAPTER - LH / RH	2	\$ 84.00	<i>X</i>
4	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	<i>X</i>
5	REAR BUMPER LOCKING MECHANISM - LH / RH	2	\$ 67.00	<i>X</i>
6	REAR BUMPER SPOILER	1	\$ 264.00	<i>X</i>
7	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	<i>X</i>
8	REAR BUMPER REINFORCEMENT BEAM	1	\$ 642.00	<i>X</i>
9	FRONT BUMPER BRACKET - LH / RH	2	\$ 63.00	<i>X</i>
10	REAR PARKING AID SENSOR - INNER / OUTER	3	\$ 797.00	<i>X</i>
11	REAR PARKING AID SEAL RING	4	\$ 10.00	<i>X</i>
12	SUNDRIES <i>Alu m</i>		\$ 300.00	<i>2 m</i>
TOTAL SPARE PARTS		:	\$ 4,873.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 7,295.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 24/02/23
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT