

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0196/2023/EQ
DATE : 22-Feb-23
WIP : 64100

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/2/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR DUVVURU SURENDRANATH
ADDRESS : BLK 272D SENGKANG CENTRAL
#15-357
SINGAPORE 544272
TELEPHONE : HP +65 94569741
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070167265-02
VEHICLE NO : **SJV 2712 G**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 27/11/2020
ENGINE NO : DEM 024772
CHASSIS NO : WAUZZZF43LN016127
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Feb-23
PLACE OF ACCIDENT : SENGKANG E AVENUE NEXT TO RIVERSOUND RESIDENCE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJV 2712 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ /
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 /
4	TO RESPRAY FRONT BUMPER.	\$ 900.00	550 /
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ 3,322.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 2712 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Rebond</i>	1	\$ 2,515.00	/
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 416.00	x
3	FRONT BUMPER SECURING STRIP - LH / RH <i>new</i>	2	\$ 84.00	x
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 231.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 310.00	x
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 166.00	x
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	1	\$ 310.00	x
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 318.00	x
9	FRONT BUMPER TRIM - LH / RH	2	\$ 114.00	x
10	RADIATOR GRILLE <i>Coneled</i>	1	\$ 1,861.00	/
11	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 224.00	?
12	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 953.00	?
13	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$ 86.00	?
14	FRONT BUMPER TOP COVER	1	\$ 151.00	x
15	CAUTION SIGN STICKER	1	\$ 17.00	x
16	AIR CONDITIONER STICKER	1	\$ 9.00	x
17	FRONT BUMPER BRACKET	1	\$ 163.00	x
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 68.00	x
19	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	x
20	FRONT PARKING AID SEAL RING	4	\$ 11.00	x
SUB TOTAL SPARE PARTS		:	\$ 8,550.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJV 2712 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	HEADLIGHT - LH / RH <i>Not in</i>	2	\$ 17,332.00	<i>X</i>
22	LIFT CYLINDER - LH / RH <i>Not in</i>	2	\$ 488.00	<i>X</i>
23	LIFT CYLINDER CORRUGATED PIPE	1	\$ 111.00	<i>X</i>
24	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 22.00	<i>X</i>
25	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 76.00	<i>X</i>
26	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 50.00	<i>X</i>
27	RADIATOR AIR GUIDE - UPPER <i>Not in</i>	1	\$ 25.00	<i>X</i>
28	FRONT NUMBER PLATE <i>Not in</i>	S/N	\$ 60.00	<i>✓</i>
29	SUNDRIES		\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 27,114.00	
TOTAL LABOUR CHARGES		:	\$ 3,322.00	
GRAND TOTAL		:	\$ 30,436.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *24/02/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT