

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 13.02.2023

Not Notion
1/1/2023
Penny After Point
9dan

D22MFL0008927

Policy No:

22.02.2023

Date:

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SLZ3841R			
1pc	Steering Air Bag		800.00 ✓
1pc	Steering Air Bag Squib <i>clock spring</i>		380.00 ✓
1pc	Driver's Seat Belt		400.00 ✓
1pc	Front Passenger Seat Belt		400.00 ✓
1pc	Front Passenger Air Bag		950.00 ✓
1pc	Dashboard		650.00 ✓
1pc	SRS ECU		580.00 ✓
2pcs	Front SRS Collusion Impact Sensors	110.00	220.00 ✓
2pcs	Wiper Arm Cover	10.00	20.00 ✓
1pc	Bonnet		380.00 ✓
2pcs	Bonnet Hinges	28.00	56.00 ✓
1pc	Bonnet Lock		65.00 ✓
1pc	Bonnet Insulator		70.00 ✓
2pcs	Bonnet Rubber Seals (Long)	45.00	90.00 ✓
2pcs	Bonnet Rubber Seals (Short)	30.00	60.00 ✓
1pc	Grille		220.00 ✓
1pc	Grille Emblem		15.00 ✓
1pc	Grille Outer Chrome Cover		240.00 ✓
2pcs	Grille Side Brackets	10.00	20.00 ✓
1pc	Grille Top Brace Bracket		70.00 ✓
1pc	Grille Outer Chrome Moulding		150.00 ✓
1pc	Front Bumper		180.00 ✓
12pcs	Front Bumper Clips	1.50	18.00 ✓
2pcs	Front Bumper Corner Retainers	10.00	20.00 ✓
1pc	Front Bumper Tow Point Cover		15.00 ✓
1pc	Front Bumper Reinforcement		190.00 ✓
2pcs	Front Bumper Reinforcement Top Protectors	10.00	20.00 ✓
1pc	Front Bumper Lower Lip		260.00 ✓
1pc	Front Bumper Lower Splash Guard		85.00 ✓
1pc	Front Bumper Fog Lamp		130.00 ✓
1pc	Front Bumper Fog Lamp Cover		20.00 ✓
1pc	Front Bumper Center Air Grille		60.00 ✓
1pc	Front Bumper Lower Rubber Guard		55.00 ✓
2pcs	Headlamps (LED)	820.00	1,640.00 ✓
2pcs	Headlamps Lower Brackets	20.00	40.00 ✓
2pcs	Headlamp Side Brackets	10.00	20.00 ✓
1pc	Air Cleaner Resonator		90.00 ✓
1pc	Front Acoustic Alerting Speaker		TBC
2pcs	Front Fenders	190.00	380.00 ✓
2pcs	Front Fender Badges (Hybrid)	42.00	84.00 ✓
		C/F	9,143.00

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Policy No: D22MFL0008927

Date: 22.02.2023

Accident Date : 13.02.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SLZ3841R			
		B/F	9,143.00
2pcs	Front Fender Protectors	130.00	260.00 ✓
1pc	Support Panel		330.00 ✓
1pc	Support Panel Top Garnish		40.00 ✓
1pc	Horn		30.00 ✓
1pc	Exterior Ambience Sensor		35.00 ?
1pc	Air Con Condenser		380.00 ✓
1pc	Air Con Condenser Fan Assy		280.00 ?
2pcs	Air Con Condenser Side Air Guides	20.00	40.00 ✓
1pc	Air Con Condenser Discharge Hose		120.00 ?
1pc	Air Con Condenser Liquide Pipe		130.00 ?
1pc	Air Con Condenser Suction Hose		100.00 ?
1pc	Air Con Compressor (Hybrid)		1,300.00 X
1pc	Radiator		720.00 ✓
1pc	Radiator Fan Assy		300.00 ?
1pc	Radiator Top Hose		20.00 ?
1pc	Radiator Lower Hose		35.00 ?
1pc	Radiator Expansion Tank		35.00 ?
1pc	Wiper Tank		50.00 ?
1pc	Engine Water Pump Assy		450.00 ?
1pc	Engine Intake Manifold		350.00 ?
1pc	Engine Starter		650.00 X
1pc	Engine Intake Manifold Air Hose		15.00 X
1pc	Engine Oil Filter		15.00 X
1pc	Engine Thermostat Assy		65.00 X
1pc	Air Cleaner Cold Air Intake Duct		30.00 ✓
1pc	Air Cleaner Box		140.00 ?
1pc	Battery Terminal Positive		55.00 X
1pc	Battery Terminal Positive Cover		15.00 X
1pc	Transmission Actuator		750.00 X
			15,883.00
	Cost Plus 10%		1,588.30
			17,471.30
	Front Number Plate		45.00 SN ✓
	Battery		150.00 SN ?
		C/F	17,666.30

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Policy No: D22MFL0008927

Date: 22.02.2023

Accident Date : 13.02.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 額 \$ cts.
	Estimate Cost of Repair to "Honda Vezel" Reg. No. SLZ3841R		
	To Conduct Electrical Check, Focus Headlamp	B/F	17,666.30
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		30.00 20d
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		120.00 10d
	To Dismantle / Replace Transmission Actuator and Supply Fluid		50.00 ✓
	To Dismantle/Renew Driver Safety Belt, Passenger Safety Belt, Steering Airbag, Dashboard Air Bag, Front SRS Crumple Zone Sensors, and Replace Airbag SRS Control Unit		250.00 X
	To Dismantle / Replace Dashboard to Facilitate Repair		200.00 ✓
	To Diagnose / Erase /Reprogram Air Bag SRS Error Code		280.00 25d
	To Provide Transportation (Towing)		250.00 20d
	Labour Charge - Panel Beating, Repairing of Front Chassis Member, Fender Inner Panel, 2x Front Door etc. Cnt, Weld Support Panel & Part Replacement		FOC
	To Spray Paint Affected Areas		1,200.00 90d
			1,500.00 110d
		Total :	21,546.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: