

ASS. REC. BY:

REF:

TOL / 23002079H

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

B7 3841R

Yr Regn:

09, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

Vozel

c.c

1496

Colour

m. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

222064

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AU3

1270242

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Farrroad

Front

Rear

R/Bal.

3

mm

R/Bal.

7

mm

L/Bal.

3

mm

L/Bal.

7

mm

D.O.A.

13/2/23

D.O.I.

27/2/2023

Survey held at

Des. of Damages: Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 13.02.2023

Not Notion
1/1/2023
Penny After Point
9dan

D22MFL0008927

Policy No: _____

22.02.2023

Date: _____

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SLZ3841R			
1pc	Steering Air Bag		800.00 ✓
1pc	Steering Air Bag Squib <i>clock spring</i>		380.00 ✓
1pc	Driver's Seat Belt		400.00 ✓
1pc	Front Passenger Seat Belt		400.00 ✓
1pc	Front Passenger Air Bag		950.00 ✓
1pc	Dashboard		650.00 ✓
1pc	SRS ECU		580.00 ✓
2pcs	Front SRS Collusion Impact Sensors	110.00	220.00 ✓
2pcs	Wiper Arm Cover	10.00	20.00 ✓
1pc	Bonnet		380.00 ✓
2pcs	Bonnet Hinges	28.00	56.00 ✓
1pc	Bonnet Lock		65.00 ✓
1pc	Bonnet Insulator		70.00 ✓
2pcs	Bonnet Rubber Seals (Long)	45.00	90.00 ✓
2pcs	Bonnet Rubber Seals (Short)	30.00	60.00 ✓
1pc	Grille		220.00 ✓
1pc	Grille Emblem		15.00 ✓
1pc	Grille Outer Chrome Cover		240.00 ✓
2pcs	Grille Side Brackets	10.00	20.00 ✓
1pc	Grille Top Brace Bracket		70.00 ✓
1pc	Grille Outer Chrome Moulding		150.00 ✓
1pc	Front Bumper		180.00 ✓
12pcs	Front Bumper Clips	1.50	18.00 ✓
2pcs	Front Bumper Corner Retainers	10.00	20.00 ✓
1pc	Front Bumper Tow Point Cover		15.00 ✓
1pc	Front Bumper Reinforcement		190.00 ✓
2pcs	Front Bumper Reinforcement Top Protectors	10.00	20.00 ✓
1pc	Front Bumper Lower Lip		260.00 ✓
1pc	Front Bumper Lower Splash Guard		85.00 ✓
1pc	Front Bumper Fog Lamp		130.00 ✓
1pc	Front Bumper Fog Lamp Cover		20.00 ✓
1pc	Front Bumper Center Air Grille		60.00 ✓
1pc	Front Bumper Lower Rubber Guard		55.00 ✓
2pcs	Headlamps (LED)	820.00	1,640.00 ✓
2pcs	Headlamps Lower Brackets	20.00	40.00 ✓
2pcs	Headlamp Side Brackets	10.00	20.00 ✓
1pc	Air Cleaner Resonator		90.00 ✓
1pc	Front Acoustic Alerting Speaker		TBC
2pcs	Front Fenders	190.00	380.00 ✓
2pcs	Front Fender Badges (Hybrid)	42.00	84.00 ✓
		C/F	9,143.00

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Policy No: D22MFL0008927

Date: 22.02.2023

Accident Date : 13.02.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Vezel" Reg. No. SLZ3841R			
		B/F	9,143.00
2pcs	Front Fender Protectors	130.00	260.00 ✓
1pc	Support Panel		330.00 ✓
1pc	Support Panel Top Garnish		40.00 ✓
1pc	Horn		30.00 ✓
1pc	Exterior Ambience Sensor		35.00 ?
1pc	Air Con Condenser		380.00 ✓
1pc	Air Con Condenser Fan Assy		280.00 ?
2pcs	Air Con Condenser Side Air Guides	20.00	40.00 ✓
1pc	Air Con Condenser Discharge Hose		120.00 ?
1pc	Air Con Condenser Liquide Pipe		130.00 ?
1pc	Air Con Condenser Suction Hose		100.00 ?
1pc	Air Con Compressor (Hybrid)		1,300.00 X
1pc	Radiator		720.00 ✓
1pc	Radiator Fan Assy		300.00 ?
1pc	Radiator Top Hose		20.00 ?
1pc	Radiator Lower Hose		35.00 ?
1pc	Radiator Expansion Tank		35.00 ?
1pc	Wiper Tank		50.00 ?
1pc	Engine Water Pump Assy		450.00 ?
1pc	Engine Intake Manifold		350.00 ?
1pc	Engine Starter		650.00 X
1pc	Engine Intake Manifold Air Hose		15.00 X
1pc	Engine Oil Filter		15.00 X
1pc	Engine Thermostat Assy		65.00 X
1pc	Air Cleaner Cold Air Intake Duct		30.00 ✓
1pc	Air Cleaner Box		140.00 ?
1pc	Battery Terminal Positive		55.00 X
1pc	Battery Terminal Positive Cover		15.00 X
1pc	Transmission Actuator		750.00 X
			15,883.00
			1,588.30
	Cost Plus 10%		17,471.30
	Front Number Plate		45.00 SN ✓
	Battery		150.00 SN ?
		C/F	17,666.30

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Policy No: D22MFL0008927

Date: 22.02.2023

Accident Date : 13.02.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 額 \$ cts.
	Estimate Cost of Repair to "Honda Vezel" Reg. No. SLZ3841R		
	To Conduct Electrical Check, Focus Headlamp	B/F	17,666.30
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		30.00 20d
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		120.00 10d
	To Dismantle / Replace Transmission Actuator and Supply Fluid		50.00 ✓
	To Dismantle/Renew Driver Safety Belt, Passenger Safety Belt, Steering Airbag, Dashboard Air Bag, Front SRS Crumple Zone Sensors, and Replace Airbag SRS Control Unit		250.00 X
	To Dismantle / Replace Dashboard to Facilitate Repair		200.00 ✓
	To Diagnose / Erase /Reprogram Air Bag SRS Error Code		280.00 25d
	To Provide Transportation (Towing)		250.00 20d
	Labour Charge - Panel Beating, Repairing of Front Chassis Member, Fender Inner Panel, 2x Front Door etc. Cnt, Weld Support Panel & Part Replacement		FOC
	To Spray Paint Affected Areas		1,200.00 90d
			1,500.00 110d
	Total :		21,546.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/02/2023 13:25 (SGT)
Reported by Driver
Date of Accident 13/02/2023 07:20 (SGT)
Exact Location of Accident Near Yishun Ave 1, Singapore
Additional Location Information Yishun ave 1 towards Yishun
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ3841R

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner KINETIC SYNERGY PTE LTD
Company Reg No 2XXXXX911Z
Email Address support@kinetic-alliance.com
Mobile Phone No (Phone) +65-97849075
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Honda
Model Vezel
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private hire
Transmission Auto
CC 1496

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Policy Number / Cover Note Number D22MFL0008927

DRIVER

Name of Driver MOHAMED FARRIS BIN MOHAMED ZAINUDDIN
NRIC No SXXXX116D
Date Of Birth 12/12/1974
Occupation Outdoor

Sketch Plan

Vishnu Ave 1



Veh A: SLZ3841R

Veh B: SLT2628D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/2/2023 @ 07:00 hrs, I was driving along Vishnu Ave 1.
Suddenly Vehicle in front of me braked, I couldn't react in time.
Thus causing my Veh A: SLZ3841R front portion to collide into
Veh B: SLT2628D rear portion. No one was injured.

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We hereby declare foregoing particulars are true in every respect.

Reg. No. 2022228352
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time.

Reporting Centre Person's Signature
Name:
NAAC/IRIN No.:

() Claim Own Policy () Claim Third Party ☒ Reporting Only
() Claim OD/TP at other workshop ()



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

911Z

Vehicle Details

Vehicle No.:

SLZ3841R

Vehicle to be Exported:

No

Intended Deregistration Date:

21 Feb 2023

Vehicle Make:

HONDA

Vehicle Model:

VEZEL HYBRID 1.5X AUTO

Primary Colour:

Silver

Manufacturing Year:

2017

Engine No.:

LEB5970269

Chassis No.:

RU31270242

Maximum Power Output:

112.0 kW (150 bhp)

Open Market Value:

\$23,902.00

Original Registration Date:

30 Apr 2018

First Registration Date:

30 Apr 2018

Transfer Count:

1

Actual ARF Paid:

\$15,463.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Apr 2028

PARF Rebate Amount:

\$11,597.00

Intended COE Rebate Details

COE Expiry Date:

29 Apr 2028

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$39,000.00

COE Rebate Amount:

\$20,236.00

Total Rebate Amount:

\$31,833.00

The information contained herein is correct as at 21 Feb 2023

OK