

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation I	nternationale Des Experts En A	Automo	bileCS3/ASM22007286/
	AXA INSURANCE			Ref:	<del>000/A0M22007200/Eqy</del> 3
	8 SHENTON WAY	_	ı	Date:	<del>01/00/2022 </del> 23/02/2023
			(	Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMG 1343M	Veh. Inspected		FD 6997S
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M047CD	Excess (\$)		0.00
	Assign From	LOW GARNET	Assign Date		<del>-01/09/2022</del> 23/02/2023
2.		Vehic	le Particulars & Conditio	n	
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
1.	Description of Damages				
5.	General Information				
	Accident Date	22/07/2022	Inspection Date	!	01/08/2022
	Survey held at	INFINITY MOTOR PTE			
	1 SOON LEE STREET, #01-37, PIONEER CENTRE, SINGAPORE 627605				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				