



AKA AUTO PTE LTD
25 KAKI BUKIT ROAD 4,
#05-36, #05-37
SYNERGY @ KB
5417800
H: 81880754
ROC: 201700008R

TP Allianz
Ezlyna

22/2/23

ESTIMATED REPAIR CHECKLIST

TO :	VEHICLE REGISTRATION NO.: SMQ3900P
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: HONDA / FIT
CLAIM TYPE : OD PARTY CLAIM	CHASSIS NUMBER: GK33417362
ACCIDENT DATE/TIME : 22 Feb 2023	CONTACT PERSON :

PARTS	QTY	PER UNIT	PRICES
1. REAR BUMPER <i>Defect</i>	1	\$ 986.90	\$ 986.90 525
2. REAR BUMPER SIDE RETAINER <i>Ken</i>	2	\$ 68.40	\$ 136.80 70
3. REAR BUMPER WEATHERSTRIP <i>Ken</i>	1	\$ 122.20	\$ 122.20
4. REAR BUMPER REINFORCEMENT <i>Ken</i>	1	\$ 455.00	\$ 455.00
5. REAR TAIL GATE <i>Defect</i>	1	\$ 1,312.00	\$ 1,312.00 825
6. REAR TAIL GATE WEATHERSTRIP <i>Ken</i>	1	\$ 120.50	\$ 120.50
7. REAR TAIL GATE INNER TRIM BOARD <i>Ken</i>	1	\$ 456.30	\$ 456.30
8. TAIL GATE LOCK <i>Defect</i>	1	\$ 326.10	\$ 326.10 225
TAIL GATE HONDA LOGO <i>Fit. Ken</i>	1	\$ 76.20	\$ 76.20 45
Sub total		SUBTOTAL :	\$ 3,992.00
Less 20%		LESS 20% :	\$ 1,203.20
Total List		PARTS TOTAL :	\$ 2,788.80

SPECIAL NETT	QTY	PER UNIT	PRICES
1. REAR BUMPER CLIPS <i>Ken</i>	1	\$ 50.00	\$ 50.00 30
1. TAILGATE INNER TRIM BOARD CLIPS <i>Ken</i>	1	\$ 50.00	\$ 50.00
Sub total		S/N TOTAL :	\$ 100.00

LABOUR CHARGES	PRICES	ADJUSTMENT
1. PANEL BEATING	\$ 1,300.00	400
2. SPRAY PAINTING	\$ 1,200.00	400
3. WIRING	\$ 50.00	30
4. TO SPRAY TUFF COAT	\$ 150.00	30
5. TO REMOVE REVERSE SENSOR	\$ 100.00	50
LABOR TOTAL :		\$ 2,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/s 23/02/23

04 Days

Total: 2444.40
1/s: 1950