

AUTOWORX HOUSE

C/O 176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7423

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Date: 23/2/2023

Not Authorized
1/1/2023
McQueen After Paying
6 days

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA AXIO / SKZ 8576K		
1 pc	rear boot lid	946.40
1 pc	rear boot lid lock	287.50
1 pc	rear boot lid lock catch	55.30
1 pc	rear boot emblem ' G '	54.40
1 pc	rear boot emblem ' AXIO '	78.60
1 pc	rear boot emblem ' COROLLA '	69.70
1 pc	rear boot emblem logo	68.10
1 pc	rear boot outer garnish	296.30
1 pc	rear boot weatherstrip	390.70
1 pc	rear boot inner trim	235.10
2 pcs	rear boot hinge @ 195.50	391.00
1 pc	rear end panel	574.40
1 pc	rear end panel garnish	325.00
2 pcs	rear tail lamp assy @ 763.60	1,527.20
2 pcs	rear tail lamp housing panel @ 374.50	749.00
2 pcs	rear tail lamp side clip @ 6.50	13.00
1 pc	rear bumper	1,052.90
2 pcs	rear bumper side retainer @ 56.00	112.00
2 pcs	rear bumper impact bracket @ 179.00	358.00
2 pcs	rear bumper corner retainer @ 87.60	175.20
2 pcs	rear bumper side reflector @ 165.00	330.00
2 pcs	reverse sensor @ 268.00	536.00
1 pc	rear spare tyre panel	687.60
1 pc	rear spare tyre top board	367.40
1 pc	rear exhaust silencer	1,421.10
1 pc	rear exhaust silencer heat shield	345.40
Sub-total		11,447.30
Less 25%		2,861.83
Sub-total		8,585.48

	Balance carried forward		8,585.48	
1 set	reverse camera	s.nett	R 460.00	X
1 set	number plate	s.nett	R 70.00	X
	To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas.		1,000.00	7000
	To install reverse sensor and camera		120.00	600
	To check wiring system.		60.00	200
	To apply rust proofing on affected areas.		150.00	600
	To apply waterproof sealant on weilded panels.		150.00	300
	To spray painting on affected areas.		2,100.00	10000
	To replace air con components and top up gas.		nn 140.00	X
	To bench mount & align chassis frame.		nn 480.00	X
	To carry out exhaust work.		nn 140.00	X
	To install reverse sensor & camera.		Repair 80.00	X
	To remove carpet, trimming and seats to enable repair.		80.00	600
	Towing charges.		(Bill) 50.00	?
	Total		13,665.48	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: