



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKV636U

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

WIP No 63178
Reg No/Reg Date SKV636U / 28/08/2015
Date In/Mileage / 0
Chassis No WDD2050402R083891
Engine No 27491030409180
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 755 Tenorite Gr/ 041 118 Alpaca grey

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	23/02/2023/ 10:13	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : 2100426537-07 // 22-2-2023				
DRIVE IN/TP VEH NUMBER : 22-2-2023 // S1815CD - ALLIANZ				
DATE IN/DATE SURVEY:				
DIRECT SETTLEMENT BY:				
A BPILAB				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				
RESPRAY REAR BUMPER				
A BPILAB				
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
A BPILAB				
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				
M REAR BUMPER	1.00	1889.77	00.00	1889.77
M REAR BUMPER LOWER BLACK TRIM	1.00	283.67	00.00	283.67
M REAR BUMPER CHROME MOULDING	1.00	326.71	00.00	326.71
M RIVET FOR BUMPER	10.00	5.34	00.00	53.40
M LH/REAR BUMPER CHROME MOULDING	1.00	114.03	00.00	114.03
M RH/REAR BUMPER CHROME MOULDING	1.00	114.03	00.00	114.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

Authorized signatory and company stamp

Go Chee Han

DID : 6771 4336 HP : 9181 7717
mail : cheehan.go@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Nett 5,681.61
8% GST on 5681.61 454.53
Total Payable 6,136.14

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg