

REF: CPC / 23 0020821/cp

## ASSIGNMENT

100

The U/C / Chassis frame / Body Structure affected due to collision.

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin M... 18/19/20

Singapore 375722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Not Withheld

1.0, \$4157.50

Recovery After Paim

5. 'day

No. : 32786

Date : 23-Feb-2023

PAGE : 1

Vehicle Insured : GBE 4947 S  
Accident Date : 19-Feb-2023

Our Ref : 023084 (LONPAC) / THERESA

LIU ZHONGYUAN (MR)  
Singapore

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5X CVT (2016) SLH561M

|                                      |             |          |    |       |
|--------------------------------------|-------------|----------|----|-------|
| 1 pc rear bumper                     | By          | 220.00   | c  | ✓     |
| 10 pcs rear bumper clips             | @ S\$ 2.00  | 20.00    | c  | ✓     |
| 2 pcs rear bumper side (LH/RH)       | @ S\$ 85.00 | 170.00   | c  | ✓     |
| 1 pc tailgate                        | By          | 580.00   | c  | ✓     |
| 1 pc tailgate glass moulding (1set)  | By          | 75.00    | c  | ✓     |
| 1 pc tailgate outer garnish c/w logo | mtj/cm      | 165.00   | c  | ✓     |
| 1 pc tailgate lock                   | By          | 90.00    | c  | ✓     |
| 1 pc tailgate inner trimboard        | By          | 125.00   | c  | ✓     |
| 1 pc tailgate weatherstrip           | mt/cm       | 60.00    | c  | ✓     |
| 2 pcs tailgate lamp (LH/RH)          | @ S\$180.00 | 360.00   | c  | ✓     |
| 1 pc tailgate keyless antenna        | cm          | 55.00    | c  | ✓     |
| 2 pcs taillamp (LH/RH)               | @ S\$275.00 | 550.00   | c  | ✓     |
| 1 pc rear end panel                  | By          | 295.00   | c  | ✓     |
| 1 pc rear end panel top garnish      | By          | 50.00    | c  | ✓     |
| 1 pc rear buzzer                     | cm          | 80.00    | c  | ✓     |
| 1 pc rear sponge compartment         | By          | 125.00   | c  | X     |
|                                      |             | 3,020.00 |    |       |
| Add 15% :                            |             | 453.00   |    |       |
|                                      |             | 3,473.00 |    |       |
| 1 pc reverse sensor assy             | By          | 220.00   | sn | 200sn |
| 1 pc tailgate glass sealant          | By          | 40.00    | sn | ✓     |
| 1 pc tailgate glass damping seal     | By          | 20.00    | sn | ✓     |

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

800.00 600d

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Cont Page 2 ...



金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Road, #02-18/19/20

Sin Ming Road, Singapore

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : GBE 4947 S  
Our Ref : 023084

Page : 2  
No. : 32786

To remove and refit reverse sensor  
assy.

60.00 50/

To transfer tailgate's fittings

80.00 60/

To remove and refit rear windscreen  
glass and conduct water leak test

120.00 ✓

To putty and respray on affected  
portions.

800.00 650/

To apply undersealing

40.00 ✓

To focus taillamps. To check rear  
wiring and lighting operation.

50.00 20/

Total : S\$ 5,703.00  
=====

Singapore Dollars Five Thousand Seven Hundred  
and Three Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.