

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sim Lim Street, Singapore 18/19/20

Singapore 375722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Not Withheld

1/1 Rep &

Accrue After Paint

5-6 days

Vehicle Insured : GBE 4947 S  
Accident Date : 19-Feb-2023

No. : 32786

Date : 23-Feb-2023

Our Ref : 023084 (LONPAC) / THERESA

PAGE : 1

LIU ZHONGYUAN (MR)  
Singapore

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5X CVT (2016) SLH561M  
=====

1 pc rear bumper		220.00	c	✓
10 pcs rear bumper clips	@ S\$ 2.00	20.00	c	✓
2 pcs rear bumper side (LH/RH)	@ S\$ 85.00	170.00	c	✓
1 pc tailgate		580.00	c	✓
1 pc tailgate glass moulding (1set)		75.00	c	✓
1 pc tailgate outer garnish c/w logo		165.00	c	✓
1 pc tailgate lock		90.00	c	✓
1 pc tailgate inner trimboard		125.00	c	✓
1 pc tailgate weatherstrip		60.00	c	✓
2 pcs tailgate lamp (LH/RH)	@ S\$180.00	360.00	c	✓
1 pc tailgate keyless antenna		55.00	c	✓
2 pcs taillamp (LH/RH)	@ S\$275.00	550.00	c	✓
1 pc rear end panel		295.00	c	✓
1 pc rear end panel top garnish		50.00	c	✓
1 pc rear buzzer		80.00	c	✓
1 pc rear sponge compartment		125.00	c	X
		3,020.00		
	Add 15% :	453.00		
		3,473.00		

- 1 pc reverse sensor assy  
1 pc tailgate glass sealant  
1 pc tailgate glass damping seal

2023  
220.00 sn  
40.00 sn  
20.00 sn

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

800.00 ?

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Cont Page 2 ...

Acknowledged by Repairer

ature:

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming Drive

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : GBE 4947 S

Our Ref : 023084

Page : 2

No. : 32786

To remove and refit reverse sensor assy.	60.00 50/
To transfer tailgate's fittings	80.00 60/
To remove and refit rear windscreen glass and conduct water leak test	120.00 ✓
To putty and respray on affected portions.	800.00 650/
To apply undersealing	40.00 7
To focus taillamps. To check rear wiring and lighting operation.	50.00 20/

Total : S\$ 5,703.00  
=====

Singapore Dollars Five Thousand Seven Hundred  
and Three Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.