

ASS. REC. BY:

REF:

AG/23002094/Ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGE9562B Yr Regn: 03, 06

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1799

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 314022 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD16206S205711

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: 215/45R17

R: Roadstone

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 23/2/23 D.O.I. 27/2/2023

Survey held at _____

Des. of Damages: Frt Rear / OIS / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/4 / 11:30 @ 535d Carhu

Date/Time, File Pass to?

: Prell. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Transportation

S - RS. SF

Paints

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Attn: Kenneth Ky

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SGE9562B
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

Estimate No: ES2300199/YISHUN
 Date: 23 Feb 2023
 Policy No: 5118677649-02
 Veh Reg No: SGE9562B
 Make/Model: HONDA HONDA CIVIC
 1.8L A

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 23/02/2023
 TP Veh Reg No: SMZ8329J

NOT Authorized
 1 Pump @ 5350/-
 Resurvey After Paint
 10 days

Chassis No: JHMFD16206S205711
 Engine No: R18A11020133
 Reg. Date: 29/03/2006

Estimate Repair Cost to Vehicle No :SGE9562B

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER	638.00	1 PC	By 638.00	✓
2 REAR BUMPER LH SIDE RETAINER	18.70	1 PC	Oil 18.70	✓
3 REAR BUMPER CLIPS	3.80	6 PCS	na 22.80	✓
4 REAR BOOT	770.70	1 PC	na 770.70	✓
5 REAR BOOT LOGO	27.40	1 PC	na 27.40	✓
6 REAR BOOT INNER LOCK	233.50	1 PC	na 233.50	✓
7 REAR BOOT INNER RUBBER	88.90	1 PC	Oil/na 88.90	508.90 #44.45 Sn
8 REAR BOOT LH REFLECTOR	140.90	1 PC	na 140.90	✓
9 REAR BOOT RH REFLECTOR	140.90	1 PC	CM 140.90	✓
10 REAR BOOT HINGE	59.10	1 PC	na 59.10	X
11 REAR BOOT INNER SPONGE	157.10	1 PC	na 157.10	X
12 REAR BOOT INNER SPONGE CLIPS	4.30	6 PCS	na 25.80	X
13 REAR BOOT EMBLEM	35.40	1 PC	na 35.40	✓
14 REAR END PANEL	273.60	1 PC	By 273.60	✓
15 REAR END PANEL INNER TOP GARNISH	134.40	1 PC	mg 134.40	✓
16 TAILLAMPS	297.60	2 PCS	na 595.20	✓
17 TAILLAMP TOP BOARD	343.60	1 PC	na 343.60	X
18 REAR RH FENDER INNER GARNISH	290.70	1 PC	na 290.70	X
19 REAR WINDSCREEN GLASS MOULDING	54.00	1 PC	na 54.00	✓
20 REAR LH FENDER	873.90	1 PC	na 873.90	✓
			4,924.60	
		Less 20%	984.92	3,939.68
Special Net				
21 REAR WINDSCREEN GLASS GUM	40.00	1 PC	na 40.00	✓
22 REVERSE SENSOR	200.00	1 PC	CM 200.00	✓
			240.00	240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES2300199/YISHUN
 Date: 23 Feb 2023
 Policy No: 5118677649-02
 Veh Reg No: SGE9562B
 Make/Model: HONDA HONDA CIVIC
 1.8L A
 Chassis No: JHMFD16206S205711
 Engine No: R18A11020133
 Reg. Date: 29/03/2006

WS Ref: TP/AIG
 Claim Type: Third Party
 Accident Date: 23/02/2023
 TP Veh Reg No: SMZ8329J

Estimate Repair Cost to Vehicle No :SGE9562B

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
23 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
24 PANEL BEATING	1,600.00	1 LA	1,600.00	1400
25 PUTTY & RESPRAY ON REAR BOOT,HINGES,REAR PANEL,REAR BOTH FENDERS,REAR BUMPER	1,200.00	1 LA	1,200.00	1100
26 REMOVE & REFIX REAR SEAT,CARPET,GARNISH	100.00	1 LA	100.00	✓
27 RUSTPROOFING	80.00	1 LA	80.00	60
			3,100.00	3,100.00
			Total	S\$ 7,279.68
			Add GST @ 8%	582.37
			Total Amount Payable	S\$ 7,862.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Parti #3959.40
 Lens 20% 791.88
 \$3167.52
 44.45 sal
 240 sal
 Labour 2780
 #6231.97
 add supp 478.48
 #6710.45
 1/Imp @ 5350h

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department


Estimate No: ES2300199 /YISHUN
Date: 01 Mar 2023
Policy No: 5118677649-02
Veh Reg No: SGE9562B
Make/Model: HONDA HONDA CIVIC
1.8L A
Chassis No: JHMFD16206S205711
Engine No: R18A11020133
Reg. Date: 29/03/2006

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 23/02/2023
TP Veh Reg No: SMZ8329J

Estimate Repair Cost to Vehicle No :SGE9562B

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 PETROL TANK	598.10	1 PC	<i>cm</i> 598.10 ✓	
		Less 20%	119.62	478.48
		Total		S\$ 478.48
		GST Amount		S\$ 38.28
		Total Amount Payable		S\$ 516.76

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE