

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

*SGE9562B*  
*TP/AIG*

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120

**Estimate No:** ES2300199/YISHUN  
**Date:** 23 Feb 2023  
**Policy No:** 5118677649-02  
**Veh Reg No:** SGE9562B  
**Make/Model:** HONDA HONDA CIVIC  
 1.8L A  
**Chassis No:** JHMFD16206S205711  
**Engine No:** R18A11020133  
**Reg. Date:** 29/03/2006

**TEL:** 64193000 **FAX:** 64153727  
**ATTN:** Motor Claim Department

*NOT Authorized*

**WS Ref:** TP/AIG  
**Claim Type:** Third Party  
**Accident Date:** 23/02/2023  
**TP Veh Reg No:** SMZ8329J

*1/1 Pump &  
 Primary After Pain  
 10 days*

### Estimate Repair Cost to Vehicle No :SGE9562B

Description	U/Price	Quantity	List Price S\$	Amount S\$
<b>List Price</b>				
1 REAR BUMPER	638.00	1 PC	638.00	✓
2 REAR BUMPER LH SIDE RETAINER	18.70	1 PC	18.70	✓
3 REAR BUMPER CLIPS	3.80	6 PCS	22.80	✓
4 REAR BOOT	770.70	1 PC	770.70	✓
5 REAR BOOT LOGO	27.40	1 PC	27.40	✓
6 REAR BOOT INNER LOCK	233.50	1 PC	233.50	✓
7 REAR BOOT INNER RUBBER	88.90	1 PC	88.90	50% ✓
8 REAR BOOT LH REFLECTOR	140.90	1 PC	140.90	✓
9 REAR BOOT RH REFLECTOR	140.90	1 PC	140.90	✓
10 REAR BOOT HINGE	59.10	1 PC	59.10	✗
11 REAR BOOT INNER SPONGE	157.10	1 PC	157.10	✗
12 REAR BOOT INNER SPONGE CLIPS	4.30	6 PCS	25.80	✗
13 REAR BOOT EMBLEM	35.40	1 PC	35.40	✓
14 REAR END PANEL	273.60	1 PC	273.60	✓
15 REAR END PANEL INNER TOP GARNISH	134.40	1 PC	134.40	✓
16 TAILLAMPS	297.60	2 PCS	595.20	✓
17 TAILLAMP TOP BOARD	343.60	1 PC	343.60	✗
18 REAR RH FENDER INNER GARNISH	290.70	1 PC	290.70	✓
19 REAR WINDSCREEN GLASS MOULDING	54.00	1 PC	54.00	✓
20 REAR LH FENDER	873.90	1 PC	873.90	✓
			4,924.60	
		Less 20%	984.92	3,939.68
<b>Special Net</b>				
21 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
22 REVERSE SENSOR	200.00	1 PC	200.00	✓
			240.00	240.00

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** AIG ASIA PACIFIC INSURANCE PTE LTD  
 78 SHENTON WAY  
 #07-16 AIG BUILDING  
 SINGAPORE 079120  
**TEL:** 64193000 **FAX:** 64153727  
**ATTN:** Motor Claim Department

**Estimate No:** ES2300199/YISHUN  
**Date:** 23 Feb 2023  
**Policy No:** 5118677649-02  
**Veh Reg No:** SGE9562B  
**Make/Model:** HONDA HONDA CIVIC  
 1.8L A  
**Chassis No:** JHMFD16206S205711  
**Engine No:** R18A11020133  
**Reg. Date:** 29/03/2006

**WS Ref:** TP/AIG  
**Claim Type:** Third Party  
**Accident Date:** 23/02/2023  
**TP Veh Reg No:** SMZ8329J

## Estimate Repair Cost to Vehicle No :SGE9562B

Description	U/Price	Quantity	List Price	Amount
				S\$
<b>Labour</b>				<b>S\$</b>
23 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
24 PANEL BEATING	1,600.00	1 LA	1,600.00	1400
25 PUTTY & RESPRAY ON REAR BOOT,HINGES,REAR PANEL,REAR BOTH FENDERS,REAR BUMPER	1,200.00	1 LA	1,200.00	1100
26 REMOVE & REFIX REAR SEAT,CARPET,GARNISH	100.00	1 LA	100.00	✓
27 RUSTPROOFING	80.00	1 LA	80.00	60
			3,100.00	3,100.00
<b>Total</b>				<b>S\$ 7,279.68</b>
<b>Add GST @ 8%</b>				<b>582.37</b>
<b>Total Amount Payable</b>				<b>S\$ 7,862.05</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE