

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0212/2023/EQ
DATE : 27-Feb-23
WIP : 65080

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/3/2023
YOUR INSURED VEH NO : SMK 5284 C

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR LI JIANXIAO
ADDRESS : BLK 501 SERANGOON NORTH AVE 4
#07-490
SINGAPORE 550501
TELEPHONE : HP +65 90610388
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : **SNF 6426 T**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 13/6/2022
ENGINE NO : DEM 032916
CHASSIS NO : WAUZZZF4XMA071599
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Feb-23
PLACE OF ACCIDENT : BUANGKOK DRIVE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 6426 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ASSY.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER ASSY. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00 500	
3	TO RESPRAY REAR BUMPER.	\$	900.00 550	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 2,502.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 6426 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Dehid</i>	1	\$ 2,642.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 184.00	x
3	REAR BUMPER SECURING STRIP - UPPER ?	1	\$ 133.00	?
4	REAR BUMPER SECURING STRIP - LOWER ?	1	\$ 264.00	?
5	REAR BUMPER SPOILER <i>ut</i>	1	\$ 292.00	✓
6	REAR BUMPER BRACKET - LH / RH <i>new</i>	2	\$ 482.00	x
7	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 543.00	x
8	REAR PARKING AID SEAL RING	4	\$ 11.00	x
9	REAR BUMPER REFLECTOR - LH / RH OUTER <i>3 new</i>	2	\$ 102.00	x
10	REAR BUMPER REFLECTOR - LH / RH INNER	2	\$ 102.00	x
11	EXHAUST TAIL PIPE TRIM - LH / RH <i>LH ut</i>	2	\$ 812.00	812.00 806.
12	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 1,197.00	?
13	REAR BUMPER GUIDE SECTION - LH / RH <i>3 new</i>	2	\$ 54.00	x
14	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 200.00	x
15	SUNDRIES ?		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 7,318.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 9,820.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Adrian Ling
02/03/23

Not Authorised, 03 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT