



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mdm Koh Mang Hoe 258 Wolskel Road Singapore 358041 Mobile: 96617311		
			Document No. 0				
			Document Date 24/02/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ S3	27/05/2016	SLC8569R	0	22378	67/DS/SLC8569R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104549071		1ZRY277039	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SJQ316G ACC DATE:22/02/2023 DRIVE IN:23/02/2023 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00	
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				198.00	
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				198.00	
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
5	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				1584.00	
6	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				1312.00	
7	1	S52159-0Z904 COVER, RR BUMPER	1.00	669.10		669.10	
8	2	S52563-02250 RETAINER, RR BUMPER,	1.00	72.80		72.80	
9	3	S52562-02250 RETAINER, RR BUMPER,	1.00	72.80		72.80	
10	4	S52161-0K040 PIECE, RR BUMPER	10.00	4.90		49.00	
11	5	S52023-02190 REINFORCEMENT SUB-AS	1.00	480.20		480.20	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 4,863.90
			Please acknowledge receipt of vehicle		Parts 1,343.90		GST 8.00% 389.11
					Labour 3,520.00		
					Sublet 0.00		
					Lubrication/Fluid 0.00		Less 0.00
					Others 0.00		Amount Due 5,253.01

Customer Copy