

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	21 Feb 2023 13:37	Clm Veh Model Changed		[] Merimen Administrator
2	21 Feb 2023 13:37	Clm Created	Reg No: SMP5717U. Acct Date: 2023/02/20. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SA01232L0006	[I] Merimen Administrator
3	28 Feb 2023 11:04	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	28 Feb 2023 11:04	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	28 Feb 2023 11:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	28 Feb 2023 11:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/03/09	[A] CELINE FONG
7	28 Feb 2023 11:04	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	28 Feb 2023 11:04	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	28 Feb 2023 11:04	Clm Veh Model Changed	(206231) AUDI Q5 SPORT 2.0 TFSI QU S TRONIC (A).	[A] CELINE FONG
10	28 Feb 2023 11:05	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CELINE FONG
11	28 Feb 2023 11:49	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	28 Feb 2023 11:49	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	28 Feb 2023 11:49	Clm Dtl Modified	JPJ Reg. Date: -> 2019/09/30.	[A] Elaine Kuan Hwa Meen
14	28 Feb 2023 11:49	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	28 Feb 2023 13:33	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2023/03/09	[A] SHIAU CHAN
16	28 Feb 2023 13:34	Adj Mandate Request	Cur.Req:35684.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUT HORISE REPAIR.	[A] SHIAU CHAN
17	28 Feb 2023 15:25	Clm Registration Modified	Init.Est.:->5,000 - 6,000.	[I] Hor, Yinrul
18	01 Mar 2023 10:18	Clm Registration Modified	Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 8.00.	[I] Hor, Yinrul
19	02 Mar 2023 08:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/03/09. Mandate Remarks: Vehicle may commence repair - REAR LID TAIL LIGHT - LH to polish Checked and Supplementary items to resurvey with CL EAR photos for damage and consistency. Before paint photos for all NEW	[I] Lim, Kok-Chong
20	02 Mar 2023 08:18	Adj Mandate Set	Approved:19846.00:Vehicle may commence repair - REAR LID TAIL LIGHT - LH to polish Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after r	[I] Lim, Kok-Chong

Date From  Date To  Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2922731	28 Feb 2023 11:49:11	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMP5717U		11.00

