

Vehicle Damage Assessment Report for [FBT3532H]

Estimate Created: 25/05/2023 12:23 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 25/05/2023 12:32 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Volvo	Model	XC90
Engine Type			
License Plate Number	FBT3532H	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- VEHICLE MAKE AND MODEL: HONDA CBR 150R	Insurlogic 4 (25/05/2023 12:32)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$602.90 WITH 3 WORKING DAYS	Insurlogic 4 (25/05/2023 12:27)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
LH inner cover		1	46.00	-10.00 %	41.40
Front lower cowling		1	62.00	-10.00 %	55.80
LH front side cowling		1	45.00	-10.00 %	40.50
Guard Balancer grip set		1	142.00	-10.00 %	127.80
Front signal lamp set		1	86.00	-10.00 %	77.40

Parts Subtotal 342.90

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Labour charge	RnR	180.00	0.00 %	180.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting cowling upper	Full spray	80.00	0.00 %	80.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 180.00

Paint Labor Subtotal 80.00

Labor Subtotal 260.00

Summary

Repair Cost 602.90

Discount(0 %) (0.00)

602.90

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 602.90