

SPEEDWERKZ PRIVATE LIMITED

6 Kaki Bukit Avenue #01-73, AUTOBAY, Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

not followed
27/2/23
1/5 & 3200/
3 days

VEHICLE NUMBER: SMR5773X
MAKE & MODEL: TOYOTA NOAH
DOA: 27/2/2023
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
Rear tailgate with glass mouding	1	\$1,850.00	11 X
Rear tailgate emblem (NOAH)	1	\$110.55	11 X
Rear tailgate centre chrome moulding	1	\$846.50	11 X
Rear tailgate Logo	1	\$95.20	11 X
Rear tailgate 1645.80	1	\$2,880.50	11 X
Rear tailgate lamp @1013.75	2	\$2,027.50	11 X
Rear tail lamp filler panel @589.60	2	\$1,179.20	11 X
Rear tailgate inner lock 409.90	1	\$895.50	11 X
Rear tailgate lock catch	1	\$165.20	11 X
Rear tailgate inner board	1	\$1,550.60	11 X
rear tail gate pull pocket	1	\$126.80	11 X
Rear tailgate lock eye	1	\$95.70	11 X
Rear tailgate weather strip	1	\$441.55	11 X
Rear tailgate hinges @115	2	\$230.00	11 X
Rear tailgate damper \$380.50	2	\$761.00	11 X
Rear taillamp @ 1185	2	\$2,370.00	11 X
Rear boot cover windscreen glass side garnish	1	\$365.00	11 X
Rear bootlid top spoiler	1	\$3,917.00	11 X
Rear bootlid lock auto side control sensor @452	2	\$904.00	11 X
Rear tailgate number plate light @ 46.10	2	\$92.20	11 X
Rear boot rubber	1	\$598.70	11 X
Rear bumper 1032.80	1	\$2,802.00	11 X
Rear bumper side @815	2	\$1,630.00	11 X
Rear bumper reflector @209	2	\$418.00	11 X
Rear bumper retainer @ 115	2	\$230.00	11 X
Rear bumper side retainer @145	2	\$290.00	11 X
Rear bumper inner garnish @95	2	\$190.00	11 X
Rear bumper PDC sensor @441.50 225	4	\$1,766.00	11 X
Rear end panel	1	\$1,085.00	11 X
Rear end panel top garnish	1	\$586.90	11 X
Rear fender @ 1926.00	2	\$3,852.00	11 X
Rear fender quarter glass with mouding @ 856.90	2	\$1,713.80	11 X
Rear fender under shield @ 86.90	2	\$173.80	11 X
Rear fender inner trim @986	2	\$1,972.00	11 X
Rear fender air duct @ 85.40	2	\$170.80	11 X
Rear key lock antenna	1	\$280.90	11 X
Rear floor matt	1	\$681.50	11 X
Rear floor penal	1	\$1,320.00	11 X
Rear Floor under cover @310	2	\$620.00	11 X

Rear exhaust silencer box	1	\$1,385.50	11X
Exhaust mounting @ 48.70	2	\$97.40	11X
Rear tow cover @58.85	2	\$117.70	11X

257 Less 10%
Sub Total

\$42,886.00
\$4,288.60
\$38,597.40

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
Rear windscreen glass sealant	1	\$120.00	11X
Rear reverse camera	1	\$550.00	11X
Rear number plate	1	\$45.00	11X
Rear boot cover trim board clip bumper clips	1 Set	\$50.00	11X
Rear fender trim board clip @ 50.00	2 Set	\$100.00	11X

Sub Total \$865.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
To check wiring		\$120.00	20
Apply anti rust chemical		\$200.00	30
Remove and replace rear windscreen		\$150.00	120
Remove and refix upholstery cushion seat, carpet and repair seat		\$350.00	80
Remove and replace PDC sensor		\$150.00	50
Remove and replace rear exhaust pipe		\$220.00	11X
Panel beating removing and replacing new parts		\$2,200.00	540
Tp spray painting and etc		\$1,800.00	600

Sub Total \$5,190.00

Grand Total \$44,652.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-3313-5
257
2485.12
90
1440
4015.12
202
3212