



6/4/2023

PAGE 1/2

© SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

ATTN: MARCUS.

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

WD: 11 DAYS.

Customer: CU0126882 / LONPAC
Chassis No: JHMGK3850KS213723
License No: SMK5617B
Mileage: 112791
Engine No: L13B14100904

Document No: SVO23008620
Printed By: JESHURUEBEN
Order Date: 2. March 2023
Order Time: 11:20:15 AM
Service Advisor: RUEBEN THOMAS

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 78174)						
	OWNER: TEO CHIN CHOON, BERNARD						
	OWNER INSURER: BUDGET DIRECT INSURANCE						
	ACC DATE: 27/02/2023						
	SURVEYED BY: MARCUS (LKK)						
	DATE: 27/02/2023						
	REF NO:						
	TP INSURER: LONPAC INSURANCE						
	TP VEH: YP430L						
73211-T5A-J01	GLASS SETRR.WINDSHIELD	1	625.60	25	469.20	37.54	506.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	12.30	25	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	7.60	25	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.55	7.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	9.60	129.60
68100-T5A-U10ZZ	TAIL GATE COMP	1	782.10	25	586.57	46.93	633.50
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	496.90	25	372.67	29.81	402.48
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.97	13.04
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	18.10	25	13.57	1.09	14.66
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	18.10	25	13.57	1.09	14.66
71505-T5A-J50	GARNISH,RR.BUMPER	1	41.00	25	30.75	2.46	33.21
71502-T5A-J60	COVER,R.RR.BUMPER	1	22.10	25	16.57	1.33	17.90
66100-TAR-T00ZZ	PANEL COMPRR.	1	342.90	25	257.17	20.57	277.74
63320-T5A-900ZZ	GUTTER COMP,R.RR.PILLAR	1	94.90	25	71.17	5.69	76.86
04636-T5A-300ZZ	PANEL SETR.RR.OUTSIDE	1	610.70	25	458.02	36.64	494.66
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	10.40	25	15.60	1.25	16.85
91501-T5A-901	CLIP A, QUARTER WINDSHIELD	1	3.70	25	2.77	0.22	2.99
91502-T5A-901	CLIP B, QUARTER WINDSHIELD	1	3.90	25	2.92	0.23	3.15
91503-TD4-003	CLIP C, QUARTER WINDSHIELD	1	2.50	25	1.87	0.15	2.02
NMDVR-VUEROID-2C	DVR, VUEROID 2 CHANNEL	1	343.93		343.93	27.51	371.44
76711-T5A-003	CAPPIVOT (S)	1	5.80	25	4.35	0.35	4.70
33500-T5A-J02	TAILLIGHT ASSY,R. (S)	1	258.40	25	193.80	15.50	209.30
74890-T5A-A11	GARNISH ASSY,RR LICENCE (S)	1	112.90	25	84.67	6.77	91.44
	SUM PARTS:				3,098.68	247.90	3,346.58
BOSUN	0760	1	20.00		20.00	1.60	21.60
	SUNDRIES						
BML02I	1931	1	180.00		180.00	14.40	194.40
	INSPECT RR LIGHTING MECHANISMS.						
	PERFORM WATER						
	TEST.(N)						
BA02R	EXT-YJ	1	160.00		160.00	12.80	172.80
	REMOVE & RENEW REVERSE						
	SENSORS-4 PCS (N)						
BOJSE	0760	1	200.00		200.00	16.00	216.00
	BODY JOINT SEALANT.						
BOBC	1865	1	100.00		100.00	8.00	108.00
	BODY UNDERSIDE COATING (N)						
BP00R	1865	1	150.00		150.00	12.00	162.00
	APPLY BODY UNDERSIDE COATING (N).						



PAVE 2/2
© SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	CU0126882 / LONPAC	Document No:	SVO23008620			
Chassis No:	JHMGK3850KS213723	Printed By:	JESHURUEBEN			
License No:	SMK5617B	Order Date:	2. March 2023			
Mileage:	112791	Order Time:	11:20:15 AM			
Engine No:	L13B14100904	Service Advisor:	RUEBEN THOMAS			
BG52D	EXT-YJ REMOVE & INSTALL RR. R QTR GLASS. (N)	1	300.00	300.00	24.00	324.00
BMI03D	EXT-YJ REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	325.00	325.00	26.00	351.00
BC012R	1931 RESET VEHICLE SMART ENTRY SYSTEM	1	325.00	325.00	26.00	351.00
BC011R	0760 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	325.00	325.00	26.00	351.00
BA10I	1931 INSTALL IN-CAR DASHCAM	1	325.00	325.00	26.00	351.00
BKTG02R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	540.00	540.00	43.20	583.20
BG02D	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	650.00	650.00	52.00	702.00
BKRP22M	EXT-YJ CUT & RENEW RR PANEL, GUTTER AND RR FENDER. ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM	1	4,550.00	4,550.00	364.00	4,914.00
BP06R	1865 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3,100.00	3,100.00	248.00	3,348.00
			SUM LABOUR:	11,250.00	900.00	12,150.00
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00	300.00	24.00	324.00
			SUM EXT SERVICE:	300.00	24.00	324.00
TOTAL SGD				14,648.68	1,171.90	15,820.58
Total Payable (SGD)						15,820.58

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT23001047	Page	1
Registration No	: SMK5617B	Date	: 6. Apr 2023	Customer No.	: WZL009
Chassis No	: JHMGK3850KS213723	Customer No.	: WZL009	Svc Advisor	: RUEBEN THOMAS
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Engine No	: L13B14100904	Date Time	: 6. Apr 2023 10:15:53 AM
Owner's Name	: TEO CHIN CHOON, BERNARD	Surveyor Name	:	Survey Date	:
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/2/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	SUPPLEMENTARY						
76711-T5A-003	CAPPIVOT	1	5.80	25	4.35	0.35	4.70
33500-T5A-J02	TAILLIGHT ASSY,R.	1	258.40	25	193.80	15.50	209.30
74890-T5A-A11	GARNISH ASSY,RR LICENCE	1	112.90	25	84.67	6.77	91.44
				Sum Item	282.82	22.62	305.44

Survey By							
Date & Time				Total Amount	282.82	22.62	305.44
Excess				Total (Inclusive of GST)			305.44
Status							
Signature							

Printed on 6/4/2023 10:16:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.