

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/LPC 230022/4pa3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$))

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

During survey vehicle already dismantled because ACI surveyor survey and ask them to dismantle.

11/4/23 P/P 814648.68 : Richard Reuben.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK5617B
Chassis No : JHMGK3850KS213723
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : TEO CHIN CHOON, BERNARD
Ins Policy No. :
Date of Accident : 27/2/2023

Document No. : SQT23000583
Date : 27. Feb 2023
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : L13B14100904
Date | Time : 27. Feb 2023 8:31:43 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TEO CHIN CHOON, BERNARD OWNER INSURER: BUDGET DIRECT INSURANCE ACC DATE: 27/02/2023 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE TP VEH: YP430L						
73211-T5A-J01	GLASS SETRR.WINDSHIELD <i>shothead</i>	1	625.60	25	469.20	37.54	506.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>neu</i>	1	12.30	25	9.22	0.74	9.96
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>neu</i>	2	7.60	25	11.40	0.91	12.31
73226-SZW-000	DAMPERSTD 5X5 <i>neu</i>	1	9.10	25	6.82	0.55	7.37
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>neu</i>	2	60.00		120.00	9.60	129.60
68100-T5A-U10ZZ	TAIL GATE COMP <i>solgird</i>	1	782.10	25	586.57	46.93	633.50
74440-T5A-003	WEATHERSTRIPTAILGATE <i>su</i>	1	92.30	25	69.22	5.54	74.76
74801-T5S-K01	LOCK ASSY, TAILGATE <i>su</i>	1	91.10	25	68.32	5.47	73.79
04715-T5A-J50ZZ	FACE, RR. BUMPER <i>dis</i>	1	496.90	25	372.67	29.81	402.48
91505-TM8-003	CLIP, BUMPER <i>neu</i>	7	2.30	25	12.07	0.97	13.04
71598-T5A-J50	SPACER, L. RR. BUMPER SIDE <i>Buy</i>	1	18.10	25	13.57	1.09	14.66
71593-T5A-J50	SPACER, R. RR. BUMPER SIDE <i>Buy</i>	1	18.10	25	13.57	1.09	14.66
71505-T5A-J50	GARNISH, RR. BUMPER <i>cu</i>	1	41.00	25	30.75	2.46	33.21
71507-T5A-J60	COVER, L. RR. BUMPER <i>11</i>	1	22.10	25	16.57	1.33	17.90
71502-T5A-J60	COVER, R. RR. BUMPER <i>cu</i>	1	22.10	25	16.57	1.33	17.90
NMRS-4P-TM3040L	4PCS ACT RR. SENSOR <i>su</i>	1	320.00		320.00	25.60	345.60
84640-T5A-003ZA	LINING ASSY, RR. PANEL <i>11</i>	1	60.80	25	45.60	3.65	49.25
84651-TAR-Z03ZA	LINING ASSYL. TRUNK <i>11</i>	1	180.80	25	135.60	10.85	146.45
84601-TAR-Z03ZA	LINING ASSYR. TRUNK <i>11</i>	1	180.80	25	135.60	10.85	146.45

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	Document No.	: SQT23000583	Page	2
Registration No	: SMK5617B	Date	: 27. Feb 2023		
Chassis No	: JHMGK3850KS213723	Customer No.	: WZL009		
Model	: JAZZ 1.3LXR CVT 19YM (EURO 6)	Svc Advisor	: RUEBEN THOMAS		
Owner's Name	: TEO CHIN CHOON, BERNARD	Engine No	: L13B14100904		
Ins Policy No.	:	Date Time	: 27. Feb 2023 8:31:43 AM		
Date of Accident	: 27/2/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84521-T5A-901ZA	LID ASSYS PARE TIRE <i>11</i>	1	203.10	25	152.32	12.19	164.51
84400-T5H-H02ZA	SHELF ASSY, RR. <i>11</i>	1	241.80	25	181.35	14.51	195.86
66100-TAR-T00ZZ	PANEL COMPR. <i>Body ID</i>	1	342.90	25	257.17	20.57	277.74
63320-T5A-900ZZ	GUTTER COMP, R.RR. PILLAR <i>Body ID</i>	1	94.90	25	71.17	5.69	76.86
04636-T5A-300ZZ	PANEL SET R.RR. OUTSIDE <i>8uc</i>	1	610.70	25	458.02	36.64	494.66
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>11</i>	2	10.40	25	15.60	1.25	16.85
91501-T5A-901	CLIP A, QUARTER WINDSHIELD <i>11</i>	1	3.70	25	2.77	0.22	2.99
91502-T5A-901	CLIP B, QUARTER WINDSHIELD <i>11</i>	1	3.90	25	2.92	0.23	3.15
91503-TD4-003	CLIP C, QUARTER WINDSHIELD <i>11</i>	1	2.50	25	1.87	0.15	2.02
65540-T5A-N00ZZ	STIFFENER COMP, R.RR. <i>11</i>	1	93.00	25	69.75	5.58	75.33
65612-T5A-300ZZ	FRAME BR. RR. <i>11</i>	1	52.90	25	39.67	3.17	42.84
65619-T5A-300ZZ	FLANGE, RR. FRAME END <i>11</i>	1	11.80	25	8.85	0.71	9.56
NMDVR-VUEROID-2C	DVR, VUEROID 2 CHANNEL <i>11</i>	1	343.93		343.93	27.51	371.44
Sum Item					4058.71	324.73	4,383.44
BO-R-COOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	24.00	324.00
Sum Ext. Service					300.00	24.00	324.00
BOSUN	SUNDRIES <i>11</i>	1	50.00	20	50.00	4.00	54.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER <i>11</i>	1	180.00		180.00	14.40	194.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N) <i>160</i>	1	200.00		200.00	16.00	216.00
BOJSE	BODY JOINT SEALANT. <i>11</i>	1	200.00		200.00	16.00	216.00
BOBC	BODY UNDERSIDE COATING (N) <i>11</i>	1	100.00		100.00	8.00	108.00
BP00R	APPLY BODY UNDERSIDE COATING (N). <i>150</i>	1	250.00		250.00	20.00	270.00
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N) <i>300</i>	1	450.00		450.00	36.00	486.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS <i>325</i>	1	450.00		450.00	36.00	486.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM <i>325</i>	1	450.00		450.00	36.00	486.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA <i>325</i>	1	450.00		450.00	36.00	486.00

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SMK5617B
Chassis No : JHMGK3850KS213723
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : TEO CHIN CHOON, BERNARD
Ins Policy No. :
Date of Accident : 27/2/2023

Document No. : SQT23000583 Page 3
Date : 27. Feb 2023
Customer No. : WZL009
Svc Advisor : RUEBEN THOMAS
Engine No : L13B14100904
Date | Time : 27. Feb 2023 8:31:43 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BA10I	INSTALL IN-CAR DASHCAM	1	450.00	325	450.00	36.00	486.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	540	650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	✓	650.00	52.00	702.00
BKRP22M	CUT & RENEW RR PANEL, GUTTER AND RR FENDER.	1	6800.00	4530	6800.00	544.00	7344.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3200.00	3100	3200.00	256.00	3456.00
Sum Labor					14530.00	1,162.40	15,692.40

Survey By

Date & Time

Excess

Status

Signature

meray lhu
27/2/23 @ 2pm.

NOT Authorised

Whaphel sekupanty

11 days.

P/P \$ 14648.68

Total Amount 18,888.71 1,511.13 20,399.84

Total (Inclusive of GST) 20,399.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 27/2/2023 11:03:12 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555

Registration No : SMK5617B

Chassis No : JHMGK3850KS213723

Model : JAZZ 1.3LXR CVT 19YM (EURO 6)

Owner's Name : TEO CHIN CHOON, BERNARD

Ins Policy No. :

Date of Accident : 27/2/2023

Document No. : SQT23001047 **Page** 1

Date : 6. Apr 2023

Customer No. : WZL009

Svc Advisor : RUEBEN THOMAS

Engine No : L13B14100904

Date | Time : 6. Apr 2023 10:15:53 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
SUPPLEMENTARY							
76711-T5A-003	CAPPIVOT <i>Torn</i>	1	5.80	25	4.35	0.35	4.70
33500-T5A-J02	TAILLIGHT ASSY,R. <i>Che</i>	1	258.40	25	193.80	15.50	209.30
74890-T5A-A11	GARNISH ASSY,RR LICENCE <i>Cut</i>	1	112.90	25	84.67	6.77	91.44
Sum Item					282.82	22.62	305.44

Survey By

Date & Time

Excess

Status

Signature

Total Amount 282.82 22.62 305.44**Total (Inclusive of GST)** **305.44****Printed on 6/4/2023 10:16:55 AM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.