

Name & Address:

GREAT AMERICAN INSURANCE COMPANY
**3 Temasek Ave.,
#16-01 Centennial Tower
Singapore 039190**

Vehicle No:

SNB5120C

Brand & Model:

MG ZS EV

Date:

5-Jul-23

Franchise:

MG

Email/Fax No:

Contact No:

Chassis/VIN No:

LSJW74093MZ145402

Contact Person (Eurokars):

Type of Claim:

THIRD PARTY

Policy No:

Date Of Registration:

26/08/2021

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER	10344162-SPRP	1	A	\$ 550.00	\$ 550.00
2	REAR BUMPER LOWER	10344164	1	A	\$ 265.00	\$ 265.00
3	SPOILER REAR BUMPER LOWER	10344180	1	A	\$ 380.00	\$ 380.00
4	REAR FINISHER RH	10014697	1	A	\$ 73.20	\$ 73.20
5	REAR FINISHER LH	10014696	1	A	\$ 73.20	\$ 73.20
6	RETAINER RH REAR	10562367	1		-	\$ 38.00
7	RETAINER LH REAR	10562366	1	A	\$ 38.00	\$ 38.00
8	COVER TOWING HOOK REAR	10344260	1	A	\$ 11.00	\$ 11.00
9	RETAINER S.S ULTRASONIC LH WITH TAPE	10345448	1	A	\$ 12.90	\$ 12.90
10	RETAINER S.S ULTRASONIC CENTER WITH TAPE	10343137	1	A	\$ 12.90	\$ 12.90
11	RETAINER S.S ULTRASONIC RH WITH TAPE	10345485	1	A	\$ 12.90	\$ 12.90
12	GROMMET SCREW	90003375	6	A	\$ 5.40	\$ 5.40
13	RIVET	30081918	4	A	\$ 8.80	\$ 8.80
14	REFLECTOR RH	10293798	1	A	\$ 120.00	\$ 120.00
15	REFLECTOR LH	10293795	1	A	\$ 120.00	\$ 120.00
16	LAMP LICENSE PLATE	10415838	1		-	\$ 36.30
17	REAR WHEEL ARCH RH	10734147	1		-	\$ 45.50
18	REAR WHEEL ARCH LH	10734127	1	A	\$ 45.50	\$ 45.50
19	SENSOR ULTRASONIC REAR	10376550-GCY	3		-	\$ 465.00
20	CAMERA VIEW MONITOR REAR	10587652	1		-	\$ 221.00
21	GROMMET SCREW	50012569	10		-	\$ 20.00
22	TAILGATE	10691021-SEPP	1	A	\$ 1,900.00	\$ 1,900.00
23	CLIP TAILGATE	50018885	2	A	\$ 2.00	\$ 2.00
24	CLIP TAILGATE	91000113	2	A	\$ 1.04	\$ 1.04
25	CLIP SPOILER	10249682	6	A	\$ 12.00	\$ 12.00
26	ANTENNA REAR	10173337	1	A	\$ 29.00	\$ 29.00
27	REAR END PANEL	10929813-SEPP	1	A	\$ 617.00	\$ 617.00
28	REAR REINFORCEMENT	10246108-SEPP	1	A	\$ 380.00	\$ 380.00
29	REAR UNDER COVER	10541537	1	A	\$ 100.00	\$ 100.00
	<u>SUPPLEMENTARY</u>				-	\$ -
30	CONTAINER ASM-R/CMPT STOW TRAY (TOOL TRAY)	10486975	1	A	\$ 88.00	\$ 88.00
31	COVER-L/GATE LAT (TAIL GATE LOCK COVER)	10318443	1	A	\$ 3.50	\$ 3.50

32	INSULATOR-R/CMPT FLR PNL (SPARE TIRE)	10480448	1	A	\$	249.00	\$	249.00
33	PANEL ASM-R/CMPT SILL TR (END PANEL TRIM)	10230145-ASA	1	A	\$	77.00	\$	77.00

Sub-Total (Parts Price) \$ 5,187.34 \$ 6,013.14

LABOUR / SERVICES CHARGES								
NO	DESCRIPTION					REVISED		PRICE
1	TO REPLACE REAR BUMPER , REAR END PANEL AND TAILGATE.					\$ 3,600.00	\$	3,960.00
2	TO RESPRAY REAR BUMPER , REAR END PANEL AND TAILGATE.					\$ 2,100.00	\$	2,520.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING					\$ 180.00	\$	180.00
4	TO TRANSFER / REPLACE REVERSE SENSOR.					\$ 200.00	\$	250.00
5	TO SUPPLY 1PC REAR NUMBER PLATE WITH CASING.					\$ 70.00	\$	70.00
6	TO RECHARGE THE CAR BY USING AC CHARGER (2 HOURS).					\$ 165.00	\$	165.00
7	For carrying out the checks, verifying and disabling connection of power (HV or 12V)" before repair and "checking, reconnection of power" after repair					\$ 165.00	\$	165.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.					\$ 200.00	\$	250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.					\$ 200.00	\$	300.00
10	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).					\$ 150.00	\$	250.00
11	SUNDRIES					\$ 20.00	\$	50.00
	<u>SUPPLEMENTARY (NECESSARY)</u>							
12	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.					\$ 560.00	\$	560.00
13	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.					\$ 120.00	\$	120.00
14	TO TRANSFER TAILGATE MECHANISM.					\$ 280.00	\$	280.00
15	TO TRANSFER REVERSE CAMERA.					\$ 280.00	\$	280.00

Survey Date & Time: 01/03/2023 @0930	Repair Days: 07 + 01 = 08	Excess:
---	----------------------------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ 8,290.00 \$ 9,400.00

		REVISED		PRICE
Parts Price	\$	5,187.34	\$	6,013.14
Labour Price	\$	8,290.00	\$	9,400.00
Total (Initial Estimate)	\$	13,477.34	\$	15,413.14
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	13,477.34	\$	15,413.14
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	13,477.34	\$	15,413.14
GST 8%	\$	1,078.19	\$	1,233.05
GRAND TOTAL	\$	14,555.53	\$	16,646.19