

李 汽 车 贸 易

GST REG NO. 201918537M

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 2-Mar-23

Estimate no.

1232

Plate No. FBT710E

Model. NC750

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 1,800.00	? 50 Local Repair	
2	FORK T-UNDER BRACKET	\$ 850.00	?X NW	
3	STEERING CONE	\$ 350.00	?X NW	
4	HANDLE BAR	\$ 320.00	Dent -	
5	HANDLE GUIDE	\$ 350.00	missing BF -	
6	BRAKE LEVER	\$ 150.00	scr	
7	BALANCER	\$ 120.00	missing BF -	
8	CRASH BAR	\$ 750.00	scr -	
9	BRAKE PEDAL	\$ 300.00	Dent -	
10	FOOTREST RIGHT	\$ 150.00	scr	
11	EXHAUST COVER	\$ 320.00	scr -	
12	MIRROR RIGHT	\$ 200.00	scr -	
13	LABOUR	\$ 500.00	300	

Fork Press - \$120

2 days

LIS

Spun 7/3/23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total : \$ 6,160.00
GST 8% \$ 5,544.00
Total: \$ 443.52
\$ 5,987.52

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.