



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|---|---|---|------------|
| HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOW GARNET | | Ref: CS/HSB23002128/Svy3e2 Date: 28/07/2023 Code: HSB | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHD 8628X | Veh. Inspected | FBT 710E |
| Policy No. | VFX/P2419140 | Coverage (\$) | 0.00 |
| Claim No. | S3M04JSE | Excess (\$) | 0.00 |
| Assign From | LOW GARNET | Assign Date | 27/02/2023 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | HONDA NC750XA | c.c | 745 |
| Engine No. | HIDDEN | Year of Reg. | 2018 |
| Chassis No. | JH2RC90A6JK202219 | Colour | BLUE |
| Odometer | - | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 120/70 R15 | MICHELIN | 2 mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | 140/70 R15 | MICHELIN | 2 mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 23/02/2023 | Inspection Date | 07/03/2023 |
| Survey held at | ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 2 Working Days | |