

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III23002132/KNY3E2**Date:** 14/06/2023**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D22MFL0008943
Claimant Vehicle No :	SLB5512D	Insured Vehicle No :	SLU364Y
Date of Loss:	25/02/2023	Nature of Claim:	TP
		Claim No:	MFL2023D0002599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB5512D	Engine No:	27492030523732
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Chassis No:	WDD2050422R135214
Reg. Date:	13/04/2016 (Man. Year: 2016)	Odometer:	87114 km
Colour:	Metallic Pearl White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		5,331.28		
Nett Amount (S\$)	0.00	5,331.28	-5,331.28	

INSPECTION

Date of Assignment:	27/02/2023	
Date Inspected:	28/02/2023	Inspected At: NINETY90 AUTOWORKS (HQ) 176 SIN MING DRIVE #02-15 Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2023)
Parts:	143	MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5512D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >