



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW8878T

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 63241
Reg No/Reg Date SLW8878T / 15/01/2021
Date In/Mileage
Chassis No W1N2476872W0688778
Engine No 28291480423362
Make/Model MB/GLB 200
Colour/Trim 029 993 Patagonia R/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	27/02/2023/ 13:26	VS	356 / Vincent Seah

Description of Goods / Services

Z REQUEST

Customer Request

M BPN SUN

POLICY NO/ACC DATE : SP2004083122-01 // 25.02.2023

DRIVE IN/EXCESS : 25.02.2023 //

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

M BPN SUN

SUNDRIES

DATE IN/DATE SURVEY:

BY/AUTHORIZED ON :

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS... NETT

A BPILAB

PANEL BEAT TO REPAIR AFFECTED AREAS. REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY ON LHF FENDER, FRONT BUMPER AND ACCIDENT AFFECTED AREA

M LEFT HEADLAMP UNIT. 3.00

M CROSS MEMBER 3.00

M FRONT SUPPORT CONNECTING CARRIER 3.00

M LEFT FENDER FRONT 3.00

M LHF EDGE GUARD 3.00

M LHF FENDER MOULDING 3.00

M LHF FENDER OUTER LINEAR 3.00

M LHF FENDER LOWER COVERING 3.00

M BRACKET, LHF FENDER (FRONT) 3.00

M FRONT BUMPER 3.00

M LHF UPP BASIC CARRIER FOR BUMPER 3.00

M LHF TOP MOUNTING RAIL 3.00

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

15.00

380.00

120.00

1440

800

3361.30

473.00

728.80

1479.57

9.42

268.90

195.71

63.46

60.47

1240.82

53.72

71.06

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6398 1818
Fax: 6779 5383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW8878T

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 63241
Reg No/Reg Date SLW8878T / 15/01/2021
Date In/Mileage
Chassis No W1N2476872W0688778
Engine No 28291480423362
Make/Model MB/GLB 200
Colour/Trim 029 993 Patagonia R/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator		
WA000001	Credit	27/02/2023/ 13:26	VS	356 / Vincent Seah		
Description of Goods / Services						
M	LH/E BUMPER BRACKET	Xan	Qty	Unit Price	Disc%	Amount
M	LH/E BASIC CARRIER FOR BUMPER	Xan	1.00	49.07	00.00	49.07
M	IMPACT ABSORBER	Xan	1.00	66.97	00.00	66.97
M	LH/F FOGLAMP COVER	Xan	1.00	174.98	00.00	174.98
M	FRONT BUMPER LOWER GRILLE	Xan	1.00	54.47	00.00	54.47
			1.00	260.96	00.00	260.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before later spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windshield in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windshield.

8% GST on 14407.68
Nett 14,407.68
1152.61

Total Payable 15,560.29

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG