



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLW8878T

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No **63241**
Reg No/Reg Date **SLW8878T / 15/01/2021**
Date In/Mileage **01/03/2023/ 40401**
Chassis No **W1N2476872W0688778**
Engine No **28291480423362**
Make/Model **MB/GLB 200**
Colour/Trim **029 993 Patagonia R/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator			
WA000001	Credit	10/03/2023/ 17:33	VS	356 / Vincent Seah			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : SP2004083122-01 // 25.02.2023
DRIVE IN/EXCESS : 25.02.2023 // \$700
DATE IN/DATE SURVEY: 01.03.2023 // 01.03.2023 RASUL-LKK 11.30AM
BY/AUTHORIZED ON : RASUL=LKK // 01.03.2023

M BPNSUN

SUNDRIES

DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT

A BPILAB

PANEL BEAT TO REPAIR AFFECTED AREAS , REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY ON LHF FENDER , FRONT BUMPER AND ACCIDENT AFFECTED AREA

X BPNEXC

INSURANCE EXCESS

X LEFT HEADLAMP UNIT

X LHF FENDER MOULDING

X FRONT BUMPER

Finalization

4 days

Confirmed & accepted by

8% GST on **Nett 6,926.02**
554.08
Total Payable 7,480.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG