



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI23002142/Uny3e2	
			Date: 05/04/2023	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBS 4369L	Veh. Inspected	SMM 6611A
	Policy No.		Coverage (\$)	0.00
	Claim No.	D23000710MFCE	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	27/02/2023
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72006303	Colour	BLACK
	Odometer	205568 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/45 R16	GITI	7 mm
	L/H Front Tyre	205/45 R16	GITI	7 mm
	R/H Rear Tyre	205/45 R16	GITI	7 mm
	L/H Rear Tyre	205/45 R16	GITI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/02/2023	Inspection Date	07/03/2023
	Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	