

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0216/2023/EQ
DATE : 28-Feb-23
WIP : 65400

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/02/2023
YOUR INSURED VEH NO : SMU 1822 Z

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MISS GUO YIXUAN GERALDINE @GUO HUITING GERALDINE
ADDRESS : 99 PASIR RIS HEIGHTS
#15-31
SINGAPORE 519291
TELEPHONE : HP +65 96540511
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5117343446-02
VEHICLE NO : **SLN 6249 U**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 11/5/2017
ENGINE NO : CHZ 338275
CHASSIS NO : WAUZZZ8VXHA115564
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Feb-23
PLACE OF ACCIDENT : PIE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 6249 U - FRONT

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	Xnn
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	?Xnn
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	?Xnn
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1250/
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDER. ?	\$ 4,000.00	1100/
TOTAL LABOUR CHARGES - FRONT		: \$ 12,060.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 6249 U - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	/
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR LID WIPER ASSY.	S/N \$	480.00	/
3	TO RENEW REAR WINDSCREEN.	S/N \$	480.00	/
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	/
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	150 /
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00	? /
TOTAL LABOUR CHARGES - REAR		:	\$ 3,240.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 6249 U - REAR

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	1000 2500
8	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND SPARE WHEEL HOUSING.	\$ 3,500.00	1100 2200
9	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00	? Xan
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES - FRONT & REAR		: \$ 23,972.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6249 U - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de/</i>	1	\$ 2,273.00	1818.40
2	FRONT BUMPER FIXING PARTS <i>Xnn</i>	1	\$ 207.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>? Xnn</i>	2	\$ 92.00	
4	FRONT BUMPER GRILLE - CENTER <i>de/</i>	1	\$ 190.00	151.60
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>? cm/</i>	1	\$ 352.00	281.20
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>? Xnn</i>	2	\$ 674.00	
7	RADIATOR GRILLE <i>cm/</i>	1	\$ 1,679.00	1343.20
8	RADIATOR GRILLE CLOSING ELEMENT <i>? cm/</i>	1	\$ 223.00	178.40
9	AIR CONDITIONER STICKER <i>ne/</i>	1	\$ 9.00	7.12
10	CAUTION SIGN STICKER <i>ne/</i>	1	\$ 17.00	13.28
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>? Xnn</i>	2	\$ 444.00	
12	FRONT BUMPER REINFORCEMENT BEAM <i>? bt/</i>	1	\$ 974.00	719.20
13	FRONT BUMPER FOAM FILLER PIECE <i>? cm/</i>	1	\$ 224.00	178.80
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>? cm/</i>	1	\$ 144.00	115.20
15	BONNET <i>bt/</i>	1	\$ 3,434.00	2747.20
16	BONNET ATTACHMENT PARTS <i>Xnn</i>	1	\$ 182.00	
17	BONNET HINGE - LH / RH <i>Xnn</i>	2	\$ 146.00	
18	BONNET EDGE PROTECTION <i>ne/</i>	1	\$ 33.00	26.24
19	BONNET CATCH HOOK <i>Xnn</i>	1	\$ 106.00	
20	BONNET STRIKER - LH / RH <i>? Xnn</i>	2	\$ 260.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 11,663.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6249 U - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET LOCK - LH / RH <i>X nn</i>	2	\$ 481.00	
22	BONNET BOWDEN CABLE - CENTER <i>? X nn</i>	1	\$ 67.00	
23	BONNET RELEASE CABLE COVER <i>? X nn</i>	1	\$ 12.00	
24	BONNET CATCH HOOK <i>bt (lower)</i>	1	\$ 75.00	<i>59.92</i>
25	FRONT PLENUM CHAMBER COVER <i>X</i>	1	\$ 211.00	
26	HEADLIGHT - LH / RH <i>? X nn</i>	2	\$ 12,464.00	
27	FRONT FENDER - LH / RH <i>repair</i>	2	\$ 2,024.00	
28	FRONT FENDER RIVET <i>X nn</i>	16	\$ 64.00	
29	FRONT FENDER CLOSING ELEMENT - LH / RH <i>X nn</i>	2	\$ 146.00	
30	FRONT FENDER BRACKET - LH / RH <i>X nn</i>	2	\$ 144.00	
31	FRONT FENDER BRACE - LH / RH <i>X nn</i>	2	\$ 228.00	
32	FRONT WHEEL HOUSING LINER - LH / RH <i>X nn</i>	2	\$ 396.00	
33	LIFT CYLINDER - LH / RH <i>X nn</i>	2	\$ 330.00	
34	LIFT CYLINDER HOSE <i>X nn</i>	1	\$ 81.00	
35	LIFT CYLINDER WASH WATER RESERVOIR <i>X nn</i>	1	\$ 231.00	
36	LOCK CARRIER MOUNTING <i>? X nn</i>	1	\$ 854.00	
37	OUTSIDE TEMPERATURE SENSOR BRACKET <i>? ann</i>	1	\$ 22.00	<i>17.36</i>
38	A/C CONDENSER <i>? X nn</i>	1	\$ 641.00	
39	A/C CONDENSER REFRIGERANT LINE <i>? X nn</i>	1	\$ 627.00	
40	A/C CONDENSER REFRIGERANT LINE <i>? X nn</i>	1	\$ 503.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 19,601.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6249 U - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	A/C CONDENSER REFRIGERANT LINE ? <i>xan</i>	1	\$ 574.00	
42	ADDITIONAL RADIATOR ? <i>xan</i>	1	\$ 967.00	
43	RADIATOR ? <i>xan</i>	1	\$ 1,099.00	
44	RADIATOR BRACKET - LH / RH UPPER ? <i>xan</i>	2	\$ 92.00	
45	RADIATOR BUSH - LH / RH LOWER ? <i>xan</i>	2	\$ 22.00	
46	READY-MIX COOLANT ? <i>xan</i>	6	\$ 326.00	
47	RADIATOR AIR GUIDE - LH / RH ? <i>cm</i>	2	\$ 62.00	48.64
48	RADIATOR AIR GUIDE SEAL - RH OUTER ? <i>xan</i>	1	\$ 10.00	
49	RADIATOR AIR GUIDE - UPPER CENTRE ? <i>cm</i>	1	\$ 20.00	15.52
50	AIR INLET COVER ? <i>xan</i>	1	\$ 31.00	
51	RADIATOR AIR DUCT ? <i>xan</i>	1	\$ 60.00	
52	RADIATOR AIR DUCT ? <i>xan</i>	1	\$ 21.00	
53	RADIATOR WATER DRAINAGE HOSE ? <i>xan</i>	1	\$ 38.00	
54	RADIATOR AIR GUIDE ? <i>xan</i>	1	\$ 71.00	
55	FRONT NUMBER PLATE <i>41</i>	S/N	\$ 60.00	
SUB TOTAL SPARE PARTS - FRONT		:	\$ 34,717.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6249 U - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>de /</i>	1	\$ 2,328.00	<i>1862.40</i>
2	REAR BUMPER FIXING PARTS <i>? xan</i>	1	\$ 213.00	
3	REAR BUMPER SPOILER <i>de /</i>	1	\$ 279.00	<i>223.20</i>
4	REAR WHEEL HOUSING LINER ADAPTER - LH / RH <i>? xan</i>	2	\$ 90.00	
5	REAR BUMPER LOCKING MECHANISM - LH / RH <i>? xan</i>	2	\$ 34.00	
6	REAR BUMPER REFLECTOR - LH / RH <i>? xan</i>	2	\$ 72.00	
7	REAR OUTER TAIL LIGHT - LH / RH <i>? xan</i>	2	\$ 2,060.00	
8	REAR INNER TAIL LIGHT - LH / RH <i>? xan</i>	2	\$ 2,060.00	
9	REAR LICENCE PLATE LIGHT - LH / RH <i>x xan</i>	2	\$ 211.00	
10	REAR BUMPER SIDE REINFORCEMENT <i>? can /</i>	1	\$ 680.00	<i>543.60</i>
11	REAR BUMPER BRACKET - LH / RH <i>can /</i>	2	\$ 67.00	<i>51.52</i>
12	REAR BUMPER GUIDE SECTION - LH / RH <i>can /</i>	2	\$ 158.00	<i>125.92</i>
13	REAR PARKING AID SENSOR - INNER / OUTER <i>? xan</i>	2	\$ 543.00	
14	REAR PARKING AID SEAL RING <i>x xan</i>	4	\$ 11.00	
15	REAR BUMPER WIRING SET <i>? xan</i>	1	\$ 578.00	
16	REAR LID <i>bt /</i>	1	\$ 3,373.00	<i>2698.40</i>
17	REAR LID ATTACHMENT PARTS <i>? xan</i>	1	\$ 326.00	
18	REAR LID HINGE - LH / RH <i>? xan</i>	2	\$ 350.00	
19	REAR LID FLAP GASKET <i>na /</i>	1	\$ 242.00	<i>193.20</i>
20	REAR LID LOCK <i>x nn</i>	1	\$ 196.00	
SUB TOTAL SPARE PARTS - REAR			\$ 13,871.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6249 U - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR LID FLAP LOCK COVER CAP <i>Xnn</i>	1	\$ 9.00	
22	REAR LID LOCK ACTUATOR PUSH BUTTON <i>Xnn</i>	1	\$ 222.00	
23	PACKING ADHESIVE <i>ne /</i>	1	\$ 22.00	<i>16.88</i>
24	REAR LID LOCK STRIKER <i>Xnn</i>	1	\$ 104.00	
25	AUDI EMBLEM <i>ne /</i>	1	\$ 152.00	<i>121.60</i>
26	"A3" INSCRIPTION <i>ne /</i>	1	\$ 110.00	<i>87.60</i>
27	"TFSI" INSCRIPTION <i>ne /</i>	1	\$ 110.00	<i>87.60</i>
28	REAR WINDOW <i>ne / plus? /</i>	1	\$ 961.00	<i>768.40</i>
29	WINDOW PRIMER <i>ne /</i>	1	\$ 24.00	<i>18.80</i>
30	REAR SPOILER FIXING PARTS <i>ne Xmm</i>	1	\$ 194.00	
31	REAR SPOILER FOAM STRIPS <i>ne /</i>	1	\$ 162.00	<i>129.20</i>
32	REAR CROSS PANEL <i>?bt /</i>	1	\$ 273.00	<i>218.40</i>
33	REAR CROSS PANEL REINFORCEMENT <i>?H /</i>	1	\$ 1,244.00	<i>995.20</i>
34	REAR CROSS PANEL CONNECTING PLATE - LH / RH <i>?Xnn</i>	2	\$ 102.00	
35	REAR SILENCER <i>? Xnn</i>	1	\$ 990.00	
36	REAR SILENCER DUAL CLIP <i>? Xnn</i>	1	\$ 66.00	
37	EXHAUST SYSTEM RETAINER <i>? Xnn</i>	2	\$ 105.00	
38	EXHAUST TAIL PIPE CHROME TRIM <i>SCA /</i>	1	TBC 72	<i>57.60</i>
39	REAR SILENCER HEAT SHIELD <i>bt /</i>	1	\$ 185.00	<i>147.60</i>
40	REAR CROSS PANEL TRIM <i>? Xnn</i>	1	\$ 181.00	
SUB TOTAL SPARE PARTS - REAR		:	\$ 5,216.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 6249 U - REAR

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	ACRYLIC SEALANT ? <i>new</i> /	S/N	\$ 180.00	✓
42	CAVITY WAX ? <i>new</i> /	S/N	\$ 140.00	✓
43	STONE CHIP ? <i>new</i> /	S/N	\$ 180.00	✓
44	METAL FILLER POWDER ? <i>new</i> /	S/N	\$ 280.00	✓
45	REAR NUMBER PLATE <i>SEA</i> /	S/N	\$ 60.00	✓
46	REAR WINDSCREEN SEALANT <i>new</i> /	S/N	\$ 200.00	✓
47	SUNDRIES ? <i>new</i> /		\$ 500.00	✓ <i>54.32</i>
TOTAL SPARE PARTS - FRONT & REAR		:	\$ 55,344.00	
TOTAL LABOUR CHARGES - FRONT & REAR		:	\$ 23,972.00	
GRAND TOTAL		:	\$ 79,316.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Rasul - Hp 90010068
28/02/23 P 1530
9 days + 4 = 13 days
P/P
Resy before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT