

 $51\, \mathrm{UBI\,AVE}\, 1, \#02\text{-}25\, \mathrm{PAYA\,UBI\,INDUSTRIAL\,PARK}, \mathrm{SINGAPORE\,408933\,\,TEL:} \\ (065)\, 62563561\,\,\mathrm{FAX:} \\ (065)\, 62564315\,\,\mathrm{FAX:} \\ (067)\, 625643$

Immediate Advice

To: ALLIANZ INSURANCE Date: 22/03/2023

Survey Details:

| Date of loss | 21-Feb-2023 |
|---------------------|------------------------|
| Date of appointment | 27-Feb-2023 |
| Date of survey | 27-Feb-2023 |
| Location of survey | Tong Luck Auto Pte Ltd |

Vehicle Details:

| Claim Type: | THIRD PARTY CLAIM | |
|----------------------|----------------------|--|
| Vehicle number | SLF1936U | |
| Make and Model | MERCEDES BENZ CLA180 | |
| Date of registration | 17-Nov-2020 | |
| | | |
| Market Value | \$ 160,000.00 | |
| Parf Rebate | \$ 57,866.00 | |
| Nett Loss | \$ 102,134.00 | |

Repair details:

| Initial Estimate | 10,245.80 |
|------------------|-----------|

Proposed/Revised repair cost:

| Parts | \$ 1,435.20 |
|-------------------------|----------------|
| Check items (estimate) | \$ - |
| Labour | \$ 1,140.00 |
| Total | \$ 2,575.20 |
| Lump Sum(if applicable) | \$ - |

| Number of days for repair | 4.0 |
|---------------------------|-----|
|---------------------------|-----|



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

| Based on TP's video fotoage - Liability 100% BOLA 15, OI cut into |
|---|
| TP's lane due to contruction works ahead and collided onto TP which |
| was travelling straight. |
| |

Mandate:

| Liability(TP) | 100% | | |
|----------------------|------|----------|----------------|
| Proposed repair cost | \$ | 2,781.22 | w/GST |
| Loss of use | \$ | 300.00 | 5 days x \$60 |
| Loss of rental | \$ | 500.00 | 5 days x \$100 |
| Loss of income | \$ | - | |
| LTA search fees | \$ | 26.75 | |
| Others | TBA | | |
| Proposed Total | \$ | 3,307.97 | |