

REF: C72/23002143/Kp

ASSIGNMENT

Others

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Front		Rear	
R/Bal.	9 mm	R/Bal.	7 mm
L/Bal.	9 mm	L/Bal.	7 mm
D.O.A.	7/2/23	D.O.I.	20/2/2023
Survey held at			

Date / Time	Action / Instruction
24/2	21 Sep @ 25501 Confirmed

[illegible]

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9013M*Not Authorised*
*61 Imp @ 2550/h***AAD2302-**

Vehicle No.:

Chassis No.:

UEN No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

20 FEB 2023**SHD9013M**

JTDKB3FU303075921

200303878K

TOYOTA

PRIUS

07/02/2023

SLC3218L/CHINA

01/11/2018

PART

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH
- 1 MIRROR ASSY, OUTER REAR VIEW, RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 RH RIM
- 1 HUB CAP
- 1 LH RIM
- 1 HUB CAP
- 1 COVER, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 FRONT FENDER EMBLEM RH
- 1 LINER, FRONT FENDER, RH

LIST

\$	<i>12</i>	1,641.36	X
\$	<i>na</i>	55.02	<
\$	<i>na</i>	16.91	X
\$	<i>na</i>	33.29	X
\$	<i>12</i>	139.86	X
\$	<i>12</i>	123.06	X
\$	<i>12</i>	1,161.83	X
\$	<i>12</i>	300.62	X
\$	<i>12</i>	1,814.09	X
\$	<i>12</i>	276.15	X
\$	<i>12</i>	1,995.11	X
\$	<i>12</i>	222.08	X
\$	<i>12</i>	1,995.11	X
\$	<i>12</i>	222.08	X
\$	<i>Bu</i>	653.31	✓
\$	<i>D11</i>	100.49	✓
\$	<i>Bu</i>	1,236.69	✓
\$	<i>na</i>	68.88	✓
\$	<i>D11</i>	260.51	✓

TOTAL \$ 12,316.42**25% \$ 3,079.10****\$ 9,237.31****Special Nett**

- 1 FRONT DOOR STICKER 'TRANS-CAB'
- 1 TYRE
- 1 TYRE

\$	<i>na</i>	100.00	
\$	<i>12</i>	300.00	X
\$	<i>12</i>	300.00	X

Trans-cab Auto Services Pte Ltd

AAD2302-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9013M

1SET FRONT FENDER LINER CLIP

1 FRONT BUMPER CLIP

1SET BUMPER RETAINER CLIP

\$	<i>nn</i>	70.00	<i>✓</i>
\$	<i>nn</i>	80.00	<i>60.00</i>
\$	<i>nn</i>	70.00	<i>X</i>

TOTAL \$ 920.00**TOTAL PARTS \$ 10,157.31****LABOUR**

To transfer of front door fittings, attachment and perform water seepage test.

\$	<i>nn</i>	170.00	<i>X</i>
----	-----------	--------	----------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		1,600.00	<i>500</i>
----	--	----------	------------

To transfer of door fittings, attachment and perform water seepage test.

\$	<i>nn</i>	170.00	<i>X</i>
----	-----------	--------	----------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$		250.00	<i>300</i>
----	--	--------	------------

To check steering geometry and computer wheel alignment

\$		220.00	<i>600</i>
----	--	--------	------------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	<i>nn</i>	380.00	<i>X</i>
----	-----------	--------	----------

Putty And Spray Painting Of The Affected Portion.

\$		1,600.00	<i>6600</i>
----	--	----------	-------------

To transfer of tire, rim and on wheel balancing.

\$	<i>nn</i>	170.00	<i>X</i>
----	-----------	--------	----------

To Check Electrical Lighting Concerned.

\$		170.00	<i>200</i>
----	--	--------	------------

To remove and refit fender fittings, attachment to facilitate bodywork repair.

\$	<i>nn</i>	350.00	<i>X</i>
----	-----------	--------	----------

TOTAL \$ 5,080.00**Over All Total \$ 15,237.31**

Trans-cab Auto Services Pte Ltd

AAD2302-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9013M

(PART-BY-PART) Repair Days

06 days

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: