

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *GBM 8626B*
 at Workshop m/s *precise*
 of _____
 Insured: *XD9269C*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *866k.*
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: *4* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 75%
 Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *GBM 8626B* Yr Regn: *15/10/18*
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *(M)*
 Make: *Toyota hiace* C.C. *2982*
 Colour: *white* A/C: Insured / Std / NI / NA
 Sp. Reading: *237141* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *JTFHT027X00245478*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *195 R15*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front *6* Rear *6*
 R/Bal. mm R/Bal. mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *17/10/22* D.O.I. *7/3/23*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *Day 11k.*

check consistency Damage consistent 7/3/23 ✓

25/4/23 1/5 & 3400 inherent year long (red to 3,33.76, 48%)

Date/Time, File Pass to?

☐

: Preli. Report

1) *4/4 train*

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *4*

Resurvey No. of Trip: *2*

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format: *TP*

Lump Sum / I.B.I. (\$) *3400*

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

TOTAL

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

19-04-2023

Accident Date : 17-10-2022

OUR REF : GBH 8626B/T/22

FOODON LOGISTICS PTE LTD

1 Enterprise Road

#03-01

Singapore 629813

Lkk - Marcus

Date In/out: 06/03/23 to 10/03/23

not Authorised
7/3/23
1/s \$3400
4 days.

ESTIMATE BILL ON VEHICLE NO. GBH 8626B

MODEL : TOYOTA HIACE

CHASSIS NO : JTFHT02PX00245478

LIST ITEM

Rear Bumper		2e/1m	371.70	/
Rear Bumper Side Retainer	2pcs @ 172.25	11	344.50	X
4pcs Rear Bumper Lower Bracket	@ 30 x 4 = 120	Self	342.50	/
1 Self Rear Bumper Clips	8pcs @ 12.90	1er	103.20	40
Tail Gate		body 177	2,165.00	/
Tail Gate Lock		Daye	371.25	/
Tail Gate Weatherstripe		11	291.40	X
Tail Gate Badge	86.10	1er	121.10	/
Tail Gate Sticker "Toyota"		1er	76.50	/
Tail Gate Sticker "Hiace"		1er	76.50	/
Tail Gate Stopper (Male / Female)	4pcs @ 43.10	11	172.40	X
Tail Lamp LH		1er	306.45	/
Tail Lamp Sealant		11	50.00	X
Rear Cornel Garnish LH		11	174.45	X
Rear Windscreen Glass Clips	6pcs @ 12.90	11	77.40	X
			5,044.35	
Less Discount 25%:			1,261.09	
			3,783.26	

SPECIAL NETT ITEM

1 set	Rèverse Sensor	not known	200 s/w	380.00
	70 Km/h Sticker	nee	10	20.00
	Rear Windscreen Glass Sealant	nee	40	60.00
	Rear Windscreen Glass Inner Seal	nee	40	50.00

LABOUR CHARGE

To check wiring system	20	50.00
To tuff coat affected areas	30	120.00
To remove & refix tail gate mechanism	60	250.00
To respray affected areas	600	850.00
To remove & refix reverse sensor	40	120.00
To renew damaged parts, straighten & repair rear end panel and aligned all parts	500	850.00

	6,533.26
GST 8%:	522.66
TOTAL AMOUNT :	7,055.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 3613.5
252
2710.12
290
1210
4250.12
22
3400

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	752K
Vehicle Details	
Vehicle No.:	GBH8626B
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2828059
Chassis No.:	JTFHT02PX00245478
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	15 Oct 2018
First Registration Date:	15 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,501.00
COE Rebate Amount:	\$15,966.00
Total Rebate Amount:	\$15,966.00

The information contained herein is correct as at 07 Mar 2023

OK