

ASS. REF. BY: Tauhin

REF:

ASSIGNMENT

2023 June
2008, June

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 46K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: WP Vehicle: IN / OUT

Veh No: SJG 3540H Yr Regn: 2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.C. 1339

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 221657 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SJH M 601850 85212812

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/S / Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 21/3/23

Survey held at Accord Auto

Des. of Damages FR / Rear / O/S / N/S / WC / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / C: _____

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133 62717433 FAX:62745715

[illegible]

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133 62717433 FAX:627457

Pg2

DOA: 25.2.2023

No	Description		Unit	List (\$)
	Special Nett			
1	REAR BUMPER & FENDER SHIELD CLIPS		1	\$ X 50.00
	Labour			
1	Spray Painting to All Affected Areas		1	\$ 400 1,500.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area		1	\$ 200 1,600.00
3	Check Wiring System & Light		1	\$ 30 100.00
4	Anti Rust Treatment		1	\$ 30 120.00
	Taylor 97495779			
	wk' 2/2/23 @ 1230pm			
	C/S Resurvey after repair			
	2 days			
	Taylor C/W Anderson			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and			
	Total (B) :		\$	3,370.00
	Grand Total:		\$	5,573.74

Date.