

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SNC4393H*Not Withheld
Primary B4 paint***LAD2302-***84810.78*

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 FEB 2023**SNC4393H**

JTDKB3FU003093051

201603575K

TOYOTA

PRIUS **GEN 4**

03/02/2023

SMX5255T/CHINA

21/10/2021

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	<i>11</i> 1,641.36 <i>X</i>
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	<i>11</i> 243.81 <i>X</i>
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	<i>11</i> 493.40 <i>X</i>
1	WEATHERSTRIP, FRONT DOOR, LH	\$	<i>11</i> 292.32 <i>X</i>
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	<i>11</i> 139.86 <i>X</i>
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	<i>11</i> 123.06 <i>X</i>
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	<i>11</i> 16.91 <i>X</i>
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	<i>11</i> 55.02 <i>X</i>
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	<i>11</i> 33.29 <i>X</i>
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	<i>11</i> 1,161.83
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	<i>11</i> 300.62
1	PANEL SUB-ASSY, REAR DOOR, LH	<i>N-C</i> \$	<i>(11)</i> 1,634.33
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	<i>11</i> 243.81
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	<i>11</i> 123.06
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	<i>11</i> 369.60
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	<i>11</i> 109.62
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	<i>11</i> 124.74
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	<i>11</i> 27.62
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	<i>11</i> 44.00
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	<i>11</i> 19.43
1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	<i>11</i> 1,161.83
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$	<i>11</i> 260.51
1	FENDER SUB-ASSY, FRONT LH	\$	1,236.69
1	BRACE SUB-ASSY, FENDER APRON, LH	\$	<i>11</i> 368.24 <i>X</i>
1	LINER, FRONT FENDER, LH	\$	<i>Dis</i> 265.55 <i>X</i>

Trans-cab Auto Services Pte Ltd**LAD2302-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SNC4393H

- 1 EMBLEM, SIDE PANEL
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 COVER, FRONT BUMPER
- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 RIM
- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

for LH wheel cap mis 222.08 ✓

	\$	<i>na</i>	68.88	✓
<i>n.c</i>	\$	<i>(Dd) R</i>	1,099.46	X
	\$	<i>Bu</i>	659.40	✓
	\$	<i>Sm</i>	120.86	X
	\$	<i>R</i>	902.16	X
	\$	<i>Sm</i>	100.91	X
	\$	<i>Sm</i>	100.49	X
	\$	<i>Sm</i>	59.85	X
	\$	<i>Sm Sm</i>	74.97	X
	\$	<i>Ref</i>	1,995.11	✓
	\$	<i>R</i>	1,695.65	X
	\$	<i>Sm</i>	624.54	X
TOTAL	\$		17,992.79	
25%	\$		4,498.20	
	\$		13,494.59	

Special Nett

- 2SET DOOR TRIM CLIP
- 2SET DOOR WEATHERSTRIP CLIP
- 1 DOOR STICKER TRANSCAB
- 1 DOOR STICKER TEL NO.
- 1SET CLIP, ROCKER PANEL MOULDING
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 2/* FENDER LINER CLIP

	\$	<i>na</i>	70.00	X
	\$	<i>na</i>	130.00	X
	\$	<i>na</i>	350.00	X
	\$	<i>na</i>	100.00	X
	\$	<i>na</i>	65.00	X
	\$	<i>na</i>	65.00	<i>65.00</i>
	\$	<i>na</i>	85.00	X
	\$	<i>na</i>	130.00	<i>130.00</i>
TOTAL	\$		995.00	

TOTAL PARTS \$ 2,300.00**LABOUR**

- To Rust-Proofing and apply undercoat Of The Affected Areas. \$ 240.00 *30/*
- To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. \$ *na* 380.00 X

Trans-cab Auto Services Pte Ltd

LAD2302-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SNC4393H

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	500
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	380.00	nn
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	720
To reinstall rear bumper parking sensor.	\$	170.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	20
To Check Electrical Lighting Concerned.	\$	170.00	20
To check steering geometry and computer wheel alignment	\$	220.00	60
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	170.00	nn X
TOTAL	\$	5,700.00	
Over All Total	\$	21,494.59	

(PART-BY-PART) Repair Days~~08~~ Days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: