



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22012937/Kqy3e2-1 Date: 03/03/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1337C	Veh. Inspected	SKR 4956R	
Policy No.		Coverage (\$)	0.00	
Claim No.	22/22/23/VC05/026765	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	28/02/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	ACR507065296	Colour	METALLIC LIGHT GREEN	
Odometer	180136 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	GITI	8 mm	
L/H Front Tyre	225/50 R18	GITI	8 mm	
R/H Rear Tyre	225/50 R18	GITI	8 mm	
L/H Rear Tyre	225/50 R18	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/12/2022	Inspection Date	29/12/2022	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	