# NCVI INVOLVING OUV MID34010 AND CIVILIAN PRIME MOVER XD7750S WITH TRAILER TRD986X AT AYE TOWARDS TUAS, CORPORATION FLYOVER, ON 13 FEB 23 AT AROUND 0948HRS






Figure A-1 — Schematic Diagram showing MID34010 travelled along AYE towards Tuas, Corporation Flyover




Figure A-2 – Schematic Diagram showing TRD986X coming to a complete stop




Figure A-3 – Schematic Diagram showing MID34010 failed to brake in time and came into contact with the rear of TRD986X



Figure B-1: Front View



Figure B-2: Rear View



Figure B-3: LHS View



Figure B-4: RHS View



Figure B-5: Scratched Front Safety Bar



Figure B-6: Dented Front LHS Tow Pin



Figure B-7: Dented Front Right Hand Side Tow Pin



Figure B-8: Dislodged Front Left Hand Side Panel



Figure B-9: Dislodged Front Right Hand Side Panel



Figure B-10: Front View of XD7750S



Figure B-13: Side View of XD7750S



Figure B-14: Scratched Rear Bumper of XD7750S



Figure B-14: Scratched Rear Bumper of XD7750S



Figure B-15: Dim Brake Lights of XD7750S/TRD986

STATEMENT OF	Lup zene	×ı				AL	IASES			T	
NRIC NO.	7 0660	2			M	MALE/FEMALE		MALG			
EMPLOYMENT	NSF DRIVING					N/	NATIONALITY		CHINESE SINION		SININAM
DIALECT		LANGUAG	26	NHLIS	Н	TE	L NO				
ADDRESS											
INTERPRETED BY			RANK		TIME		DATE			SIGN	
RECORDED BY	NICKSON NG		RANK	CPT	TIME	11 00	DATE	1302	23	SIGN	Men
there is a to maintaining a down because I could so the truck I applied with the	trailer into a safe distance is the state of the state of the brake trailer be	out of m ance wh not see earlboard that Despite	ile A if . ligh the i e mi	icle iguing there t. A vehicle p bes z om	and out is am is Z is s t ex	I we if flo y his was rlawing forf lying	es slow  the trail  ble by  approac  y down  I sto	ler ler hing hing hing	do is lis cu hen coll	sluminglet, lose, extone	end 9 911 40
did not collision.	10.			¢ 740	<i>p.</i> 14	- ATM				lay Th	1 due

Figure C1: Statement of Driver

STATEMENT OF	CPL GERRIK SOLON CHAN					Al	IASES				
NRIC NO.	ME AGE		21		M	MALE/FEMALE		MALE			
EMPLOYMENT	NSF DRIVING LICENSE NO		NO			N/	NATIONALITY		AMERICAN		
DIALECT	LANGUAGE SPOKEN			ENGLISH		TE	TEL NO				
ADDRESS		31 31 31									
INTERPRETED BY			RANK	(	TIME		DATE		SIGN		
RECORDED BY	NICKSON N	6	RAN	CP7	TIME	1100	DATE	130223	SIGN	May	
taken notice and	applied the		my down	on, and distan	Arvers	ed a	ite Re	the TO 1 best att	hed alm	edy He To	
taken notice and our OUV NO 340 Zang Xi was not	applied the 10 s front to spreading w	belies to a	ry down	on-, and distant, contr	Haveno	ed a	ita Ke	the TO 1 best att	hed alm	edy He To	
bokon adice and our OUV DU 340 Zony X was not	applied the 10°s front b	belies to a	ry down you'd come tro	or, and	House of all	ed a	wrning.	the TO 1 best att	hed alm	edy He To	

Figure C2: Statement of front passenger





Report No. J/20230213/7025

#### POLICE REPORT (NP299)

Police Station Of Origin Jurong Division HQ 2 Jurong West Avenue 5 SINGAPORE 649482 Tel No:1800-7910000

13/02/2023 09:50 - 13/02/2023 12:00

Date/Time Report Made Station Diary No. Vide Report No. Name Of Informant HENG ZENG XI ID Type / ID No. Contact No. NRIC NO / T Home/Office: Mobile: Nationality Email Address SINGAPORE CITIZEN Occupation Age Date of Birth Race NATIONAL SERVICE ARMY Male 25/01/2001 Institution/School Name Language English Date/Time Of Incident Location Of Incident

Brief details.

On 13Feb 2023, at around 0948Hrs, I was driving OUV MID34010 accompanied by front passenger CPL Gerrik. We were doing admin movement from Clementi Camp to Jurong Island. Along the way on AYE towards Tuas near exit 17, there is a trailer in front of my vehicle and I was slowing down and maintaining a safe distance while figuring out if the trailer is slowing down because I could not see if there is any visible brake light. All I could see is the tailboard light. As I was approaching closer to the trailer I realised that the vehicle is slowing down therefore I applied the brake. Despite my best effort I still collided with the trailer because when I am applying the break, the OUV did not came into complete stop in time thus resulting in the collision.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 13/02/2023 13:37
Officer In-Charge Of Case:	Classification Of Case:
1.8c	

Figure 4A: Police Report Part 1





2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20230213/7025

	<u> </u>		
Victim Person Name	HENG ZENG XI		
ID Type	NRIC NO	ID No	1066D
Gender	Male	Age	22
Race	Chinese	Language	English
Occupation	NATIONAL SERVICE ARMY	Address	
Mobile No		Is Informant A	Yes
	19.	Victim?	
	<b>C</b> A		•
Person Name	HENG ZENG XI (Informant)		

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 13/02/2023 13:37
Officer In-Charge Of Case:	Classification Of Case:
7.8 <sub>C</sub>	

Figure 4B: Police Report Part 2